



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72651
 Promised Date:
 04 NOV 25



WO #: 72651 (Appointment Date: 10 NOV 2025 - Time: 02:15pm)
 Customer Name: 60921 - GARY, BEN Completed Date: 29 JAN 26
 Invoice#: Author: BRIAN
 Stock Desc: 2025 CORTERRA 26.3RB
 Serial#: 5SFDB3128SE542673
 Chassis#: Date In: 10 NOV 25
 Miles/Hrs: Time In:
 Tag#: 6889
 Purchased Date:
 Warranty Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES WATER SYSTEM LEAKING EXTERIOR/INTERIOR WHEN CONNECTED TO CITY WATER / CHECK FRESH WATER TANK AND PUMP

CAUSE: Fill tube kinked causing tube to separate

CORRECTION: Drop underbelly to access tank at top and replace fill hose.
 3.0 hrs

Labor

Job #	Description	Total
1	WATER SYSTEM TROUBLESHOOT	N/C

Parts

Part #	Description	Qty	Price	Total
99-8106	BOARD REPAIR TAPE FOR UNDERBELLY - 1 FT	5.00	N/C	N/C
5302	SILICONE CAULK SEALANT - BLACK	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THE MONITOR READS FULL ALL THE TIME FOR FRESH WATER TANK

CAUSE: Must drop underbelly. Connections at tank very loose.

CORRECTION: Need auth to drop underbelly 3.0 minimum
 Repairs completed. Tested

Labor

Job #	Description	Total
2	MONITOR PANEL DIAGNOSE	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES THE WATER WAS LEAKING ON THE INSIDE HE WOULD LIKE TO

Customer #: 60921
 GARY, BEN



MAKE SURE THE FLOOR AND WALLS IS OK. KM

CAUSE: Visually inspected trailer. No wood damage from water apparent

CORRECTION: Completed

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES TOILET LEAKING WHEN BEING FLUSHED AT PEDAL

CAUSE: WATER VALVE AND BALL VALVE MECHANISM LEAKING

CORRECTION: REMOVED PEDAL / FOUND PIECE FOR BALL VALVE CAME APART / FOUND WATER VALVE LEAKING

WATER VALVE AND BALL VALVE MECHANISM NEEDS TO BE REPLACE OR ENTIRE TOILET

Labor

Job #	Description	Total
4	TOILET	N/C

Subtotal for Job #4: 0.00

Job #5 - External

CHECK WATER SYSTEM

Labor

Job #	Description	Total
5	DIAGNOSIS	0.00

Subtotal for Job #5: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 11 Mar 2026

Customer Signature : _____

W/O: 72651
Promised Date: 21 NOV 25



Customer #: 60921
GARY, BEN

