



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM  
Ready for Pickup: Thu Apr 9, 2026 | 8:46 AM  
Promise Time: Sun Apr 12, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222  
NO@GMAIL.COM  
1025 WI-77  
Minong, WI 54859

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 FOREST RIVER  
AVENGER 16BHX-452  
5ZT2AVEC7TG815781  
1 Mi In  
Stock #: FR26-25

**Service Advisor**  
KEVIN GOODIEL  
goodielk

A.	MISCELLANEOUS	DEALER STATES THE TOP HINGE ON CABINET DOOR UNDER KITCHEN SINK IS BROKEN	Internal Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM

1. Cabinet door may have opened during transport and swung open past the designed amount

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.25	0	0	\$0.00	\$0.00

1. Needs new hinge. Requested .3 hours

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
\$0.00	\$0.00	\$0.00	\$0.00

B.	MISCELLANEOUS	DEALER STATES THE PLUMBING VENT CAP SCREW AND RIGHT REAR CORNER EXTRUSION REQUIRE RESEAL	Internal Pay	\$0.00
----	---------------	--	--------------	--------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM

1. Small holes in self leveling sealant.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM  
Ready for Pickup: Thu Apr 9, 2026 | 8:46 AM  
Promise Time: Sun Apr 12, 2026 | 6:00 PM

<b>Customer</b> linkautomotive - 2174 PD7155200709I Customer 1235491 +1 - (715) 466 - 2222	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 FOREST RIVER AVENGER 16BHX-452 5ZT2AVEC7TG815781	<b>Service Advisor</b> KEVIN GOODIEL goodielk
---	---	---	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.08	0	0	\$0.00	\$0.00

1. Re-sealed plumbing vent and right corner rear extrusion.

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>C. MISCELLANEOUS</b>	<b>DEALER STATES UNIT DIDNT COME WITH A SEPTIC CAP FOR THE WAIST TANKS</b>	<b>Internal Pay</b>	<b>\$0.00</b>
-------------------------	--	---------------------	---------------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM

1. missing

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00  
Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0	0	0	\$0.00	\$0.00

1. Unit missing septic cap. Requested .1 hours

<b>Total Labor Sale</b> \$0.00	<b>Total Labor Cost</b> \$0.00	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
-----------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

<b>D. MISCELLANEOUS</b>	<b>DEALER STATES THE CABINET DOOR BYE KITCHEN SINK HAS A BIG SCUFF IN IT</b>	<b>Internal Pay</b>	<b>\$0.00</b>
-------------------------	--	---------------------	---------------

Job added by KEVIN GOODIEL on Tue Apr 7, 2026 | 1:20 PM





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM  
Ready for Pickup: Thu Apr 9, 2026 | 8:46 AM  
Promise Time: Sun Apr 12, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 FOREST RIVER  
AVENGER 16BHX-452  
5ZT2AVEC7TG815781

**Service Advisor**  
KEVIN GOODIEL  
goodielk

1. Cabinet door may have swung open past designed amount during transport. Cabinet broke top hinge and made 2 large gouges on outside of cabinet door at bottom hinge.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$0.00

Labor Cost: \$0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0	0	0	\$0.00	\$0.00

1. Needs new door. Requested .3 hours

Total Labor Sale  
\$0.00

Total Labor Cost  
\$0.00

Total Parts Sale  
\$0.00

Total Parts Cost  
\$0.00

Category	Sale	Cost
Labor	\$0.00	\$0.00
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$0.00</b>	<b>\$0.00</b>





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$0.00

RO# : 40344 Tag# : TG815781

Check-in: Tue Apr 7, 2026 | 1:20 PM  
Ready for Pickup: Thu Apr 9, 2026 | 8:46 AM  
Promise Time: Sun Apr 12, 2026 | 6:00 PM

**Customer**  
linkautomotive - 2174  
PD7155200709I  
Customer  
1235491  
+1 - (715) 466 - 2222

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 FOREST RIVER  
AVENGER 16BHX-452  
5ZT2AVEC7TG815781

**Service Advisor**  
KEVIN GOODIEL  
goodielk

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Tue Apr 7, 2026	3:07 PM	3:22 PM	0.25 hrs	I	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
B	MISC	Tue Apr 7, 2026	4:07 PM	4:12 PM	0.08 hrs	I	shurterc	0 hrs
Tag: Regular Hour			Reason: -					
C	MISC	-	-	-	0 hrs	I	shurterc	0 hrs
D	MISC	-	-	-	0 hrs	I	shurterc	0 hrs

