

Warranty Claim Detail

R.O. Number **72865**
 Job **1**

COMPLAINT INFORMATION	
Flat Rate Code	0532
Description	Jack-Equalizer System-Hydraulic hose fitting
Occurrences	1
Requested Hours	4.00
Authorized Hours	4.00
Fault Code	19-Fluid Leak
Vendor Responsible	89996-NEWMAR WORKMANSHIP Hours:.50

GENERAL INFORMATION	
Status	Pending Claim Submission
Date In	01/23/2026
Submit Date	01/27/2026
Authorization	No 01/30/2026
Work Complete	No
Payment	No

CUSTOMER COMPLAINT
COMMENT ENTERED ON 01/27/2026 AT 11:05 AM BY DEALER Hydraulic leak at passenger side rear

AUTHORIZATION NOTES
COMMENT ENTERED ON 01/27/2026 AT 11:45:14 AM BY ALDUNNING PICTURES FROM CASE 01059657 COMMENT ENTERED ON 01/30/2026 AT 3:20:05 PM BY CRAMSEY EMAILED FOR AUTH AND ATTACHED.

DEALER CORRECTION
COMMENT ENTERED ON 01/27/2026 AT 11:05 AM BY DEALER Both extend and retract hydraulic lines on right rear jack has pinhole in them. Spray ing fluid everywhere on retract and extend. Remove damaged hydraulic lines, replace b oth lines from front to back. Need 4.0 hours for removal of old lines, installation o f new lines. Loom and secure. Had to get hoses locally as unit was scheduled for a te st drive and walk through for a sale.

TOTALS	Requested	Authorized
Labor	740.00	740.00
Sublet	.00	.00
Parts	.00	.00
Freight	.00	.00
Adjustments	.00	.00
TOTAL	740.00	740.00
TOTAL PAID		.00

