

Claim statement

Claim	J01485843	Unit	58TBM0AK2S7533146				
Dealer account #:	296921	Chassis:	0001442629				
	MYERS RV CENTER, INC	Description;	188BHS OPEN RANGE TT				
Reference:		Registration date:	05/09/2025				
Customer:	Lopz, Johnnylee	Mileage:					
Repair line	J01485843-001	Create date:	12/22/2025	Start date	01/28/2026	Rep line desc:	Smoke Detector
Claim type	Standard	Status:	Confirmed	End date	01/28/2026	Pre auth#:	PA001304545
Claim group	WarrClaim	Status date	02/06/2026				
forkert December 22, 2025 12:26 PM approve .2							

Complaint:	Smoke detector is going off for no reason
Cause:	CompFail Smoke detector has intermittent operation
Correction:	Replace the smoke detector

Transaction type	Main Op.	Operation no	Item number	Disp. code	Adj. Reason Code	Description	Req. qty	Unit	Unit price	Req. amount	Approved quantity	Approved amount
Labor	Yes	0408001D				INTERIOR MISCELLANEOUS-REPLACE-SMOKE DETECTOR	0.20		\$179.00	\$35.80	0.20	\$35.80
Item	No		2066858	CLMNOPART		DETECTOR,SMK ALARM FIRST ALERT MOD: SMI100RV	0.00	EA	\$25.77	\$0.00	1.00	\$13.94
Item	No		9001530		Part Incorrect	50480 Smoke Detector - Lithium Battery	1.00	EA	\$13.94	\$13.94	0.00	\$0.00
Charges	No					Parts markup	1.00		\$4.18	\$4.18	1.00	\$4.18

	Labor	Parts	Charges	Total		
Total requested amount	\$35.80	\$13.94	\$4.18	\$53.92	Invoice status	Invoiced
Total adjusted	\$0.00	\$0.00	\$0.00	\$0.00	Invoiced date	2/6/2026
Total approved amount	\$35.80	\$13.94	\$4.18	\$53.92	Payment reference	457045

Claim total J01485843	Labor	Parts	Charges	Total
Total requested amount	\$35.80	\$13.94	\$4.18	\$53.92
Total adjusted	\$0.00	\$0.00	\$0.00	\$0.00
Total approved amount	\$35.80	\$13.94	\$4.18	\$53.92