



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 71914
Promised Date:
07 JUN 25



WO #: 71914

Customer Name: 60002 - BARELA JR,
FRANK

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9431 2025 OPEN RANGE

22MLS

Serial#: 58TBM0BM1S7543053

Date In: 27 JUN 25

Chassis#: 58TBM0BM1S7543053

Time In:

Miles/Hrs:

Tag#: 6749

Purchased Date: 24 JUN 25

Warranty Date: 13 JUL 25

Job #1 - Internal

COMPLAINT: TEAR ON LEFT SIDE OF RECLINER

CAUSE: Recliner/couch has a tear on the right side recliner

CORRECTION: Need to replace the right side recliner. Has a tear on the front right corner

Labor

Job #	Description	Total
1	RECLINER	N/C
Subtotal for Job #1:		0.00

Job #2 - Internal

COMPLAINT: PRIVACY CURTAIN

CAUSE: Not installed

CORRECTION: Took measurements to install the privacy curtain to insure while the curtain was closed the air conditioner vent would be in the bedroom area.

The curtain was installed in an arc around the ac vent and to not interfere with the entry door

The rail was screwed to the ceiling and curtain clipped on , the tie was attached to the wall

Work completed

Labor

Job #	Description	Total
2	PRIVACY CURTAIN INSTALL W/TRACK	N/C

Parts

Part #	Description	Qty	Price	Total
2046854	DRAPE, PRIVACY 102 X 64 TOWNSEND TRUFFLE W/ GLIDE TAPE WITH 15" TIE BACK	1.00	N/C	N/C
0229064	TRACK, CURTAIN CIELING MOUNT WHITE 144"	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

Transferred to RV*72336 on 09 JAN 26

Estimate amount was 0.00

Customer #: 60002
BARELA JR, FRANK



TWO VALANCES

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: DRIVER AND PASSENGER FENDERSKIRTS CRACKED
PICTURES ARE ON WO#71804

CAUSE: SCREWS TOO TIGHT

CORRECTION: Removed 12 screws from each fender skirt , removed the old fender skirt
Lined up the new fender skirt on each side and rescrewed them to the unit
Work completed
.80 (.40EACH)

Labor

Job #	Description	Total
4	FENDERSKIRT R&R TRAILER	161.10

Parts

Part #	Description	Qty	Price	Total
0321158	FENDER SKIRT 66.13 X 9.5 BLACK HDHE	2.00	65.38	130.76

Subtotal for Job #4: 291.86

Parts Total: 130.76
Labour Total: 161.10
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 291.86

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 09 Jan 2026

W/O: 71914
Promised Date: 27 JUN 25



Customer #: 60002
BARELA JR, FRANK

