



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72258
 Promised Date:
 07 FEB 26



WO #: 72258

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 26 FEB 26
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9603 2026 OPEN RANGE
 COLT 26RCS
 Serial#: 58TBM0BP7T76Y3054
 Chassis#: 58TBM0BP7T76Y3054
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 25 AUG 25
 Time In:

Job #1 - Warranty

COMPLAINT: Lino has glue / adhesive near recliners.

CAUSE: Adhesive on lino floor near rear recliners.

CORRECTION: Cleaned off with adhesive remover and brush .10hr

Labor

Job #	Description	Total
1	MULTIPLE LABOR CODES	89.50
Subtotal for Job #1:		89.50

Job #2 - Warranty

COMPLAINT: Water leak under kitchen sink.

CAUSE: Water leak at pipe connections under sink.

CORRECTION: All pipe connections needed to be tightened. .20hr

Labor

Job #	Description	Total
2	MULTIPLE LABOR CODES	71.60
Subtotal for Job #2:		71.60

Job #3 - Internal

COMPLAINT: Front LED light strip is missing.

CAUSE: Completely missing

CORRECTION: Found less than 1/4 inch of wire sticking out of the edge of the belt rail on the rock guard
 Removed belt rail pulled wires out
 Reconnected new wires
 Reinstalled belt rail
 Installed new light
 Resealed belt rail with silicone
 Tested the light operating correctly
 Work completed

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,





Labor		
Job #	Description	Total
3	STRIP LIGHTING R&R	N/C

Parts				
Part #	Description	Qty	Price	Total
2087249	LIGHT, STRIP WHITE FUSION 93.01" 12V	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SHOREPOWER RECEPTACLE SEPARATING AT SIDEWALL

CAUSE: Shore cord receptacle pulled away from the rear of the unit

CORRECTION: Found the shore cord receptacle had pulled away from the side of the unit at the top
 Found the screw on the left was not drilled through the side of unit but just through the decal
 Cut a piece of 1/4 plywood and put it inside the wall as a backer plate
 Reattached the receptacle
 Sealed with clear silicone
 Work complete .25

Labor		
Job #	Description	Total
4	MULTIPLE LABOR CODES	53.70

Subtotal for Job #4: 53.70

Job #PDI1 - Internal

COMPLAINT: Transferred to RV*72258-1 on 31 JAN 26
 Estimate amount was 0.00
 PRE-PDI NEW TT - 3.0

CAUSE: PDI NEEDED

CORRECTION: PDI COMPLETED

Labor		
Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: Transferred to RV*72258-1 on 31 JAN 26
 Estimate amount was 0.00
 WINTERIZE STANDARD

CAUSE: Winterize unit.

CORRECTION: Unit has been winterized.

Labor		
Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Subtotal for Job #WIN-STD: 0.00



W/O: 72258
Promised Date: 27 FEB 26

Parts Total:	0.00
Labour Total:	214.80
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	214.80

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 26 Feb 2026



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Customer Order

