



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72442
 Promised Date:
 03 OCT 25



WO #: 72442 (Appointment Date: 03 OCT 2025 - Time: 11:15am)
 Customer Name: 59318 - MONTES DE OCA, LYDIA B
 Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9434 2025 OPEN RANGE
 22MLS
 Serial#: 58TBM0BM5S7543055
 Chassis#: 58TBM0BM5S7543055
 Miles/Hrs:
 Tag#: 6799
 Purchased Date: 21 APR 25
 Warranty Date: 21 APR 25
 Date In: 03 OCT 25
 Time In:

Job #0 - External

COMPLAINT: SEE ATTACHED CUSTOMER LIST

CAUSE: None

CORRECTION: N/a

Labor

Job #	Description	Total
0	DIAGNOSIS	0.00
Subtotal for Job #0:		0.00

Job #1 - Internal

COMPLAINT: CUSTOMER STATES REFER MAKES A LOUD NOISE WHEN TURNED ON

CAUSE: Customer complaint refrigerator makes a loud noise when turned on

CORRECTION: Had the unit parked in bay 2
 Plugged unit into shore power
 Opened the slide room
 Turned the refrigerator on and closed the door
 The refrigerator never made any kind of noise at all during the jobs done on the work order
 Could not replicate

Labor

Job #	Description	Total
1	REFRIGERATOR DIAGNOSTIC TIME	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES 3 BLINDS WILL NOT STAY UP (TWO IN BEDROOM AND ONE IN KITCHEN)

CAUSE: Kitchen blind tension cord loose

Customer #: 59318
 MONTES DE OCA, LYDIA B



Left bedroom blind pulled away from the wall
Right bedroom blind tension string loose

CORRECTION: Found the kitchen blind had a loose tension cord
Adjusted the tension on the cords blind now stays up
Found the left side bedroom window blind and decor cover was pulled off the wall and a screw missing
Removed on screw set the decor cover and blind aside added screws to both sides supports set the blind
and window trim back in place and screwed back to the supports.
Then found the tension cords were loose.
Adjusted the tension cords blind now stays up and is attached to the wall.
Found the right side bedroom blind had loosed tension cords
Adjusted the tension on the cords blinds now stay up
Work completed

Labor		
Job #	Description	Total
2	WINDOW SHADE DIAGNOSE	N/C
Subtotal for Job #2:		0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES TRIM ON THE SHOWER SURROUND LOOSE (SINK SIDE)

CAUSE: Trim came loose staples pulled out

CORRECTION: Found the bottom half of the shower trim pulled away from the wall restapled the trim back
down and puttied the new staple holes
Trim secure work completed

Labor		
Job #	Description	Total
3	TRIM	N/C
Subtotal for Job #3:		0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES TWO BOTTOM KITCHEN DRAWERS ARE BINDING

CAUSE: Drawers sticking hard to open fully hanging up in the middle

CORRECTION: Found the bottom drawer the guides were very dirty and needed to be lubricated
Found the middle drawer guides were also dirty and needed to be lubricated
Also found the drawer was sticking very hard about half way out
Once the rails were cleaned and lubricated the drawers work correctly

Labor		
Job #	Description	Total
4	DRAWERS	N/C
Subtotal for Job #4:		0.00

Job #5 - Internal

COMPLAINT: CUSTOMER STATES WHEN CLOSING RECLINER (TOWARD BEDSIDE) BINDS

CAUSE: Customer complaint the recliner close to the bed binds

CORRECTION: Sat in the recliner and ran out and in 5 times in a row
The recliner moved in and out smoothly
Could not replicate

Labor		
Job #	Description	Total
5	RECLINER	N/C

W/O: 72442
Promised Date: 17 OCT 25



Customer #: 59318
MONTES DE OCA, LYDIA B





Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CUSTOMER STATES UNDERBELLY TAPE LOOSE

CAUSE: Tape over a hole in the underbelly coming off

CORRECTION: Cut the loose tape off

Foam filled the hole

Work completed

Labor

Job #	Description	Total
6	UNDERBELLY	N/C

Parts

Part #	Description	Qty	Price	Total
17150	SPRAY FOAM, GREAT STUFF (BLACK)	1.00	N/C	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES HOOD LIGHT INOPERATIVE

CAUSE: Light has broken wire

CORRECTION: Recommend replacement of the light

Found the red wire which is soldered to the inside of the light has broken

Labor

Job #	Description	Total
7	HOOD LIGHT	N/C

Subtotal for Job #7: 0.00

Job #8 - Internal

COMPLAINT: CUSTOMER STATES CHECK OVEN

- OVEN LIGHT STAYS ON THROUGH COOKING TIME
- FLAME FLICKERS WHILE COOKING

CAUSE: Customer complaint light stays on while oven is in use
 Flames flicker

CORRECTION: Turned on the propane

Turned the oven on the light is automatic on

Lite the pilot light set the temp to 350

Oven heated up quickly to 350 and maintained this temp for 30 minutes

The flame flicker was the flame coming on and off to maintain temperature

There not a switch on the oven to turn the light on and off it is a built in feature

The burner flame was good blue and even

Oven is operating correctly

Labor

Job #	Description	Total
8	OVEN DIAGNOSE	N/C

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: CUSTOMER STATES BATHROOM DOOR FELL IN TRANSIT / REINSTALLED BUT DOOR DAMAGED AND LATCH LOOSE

CAUSE: Door fell off in transit
 Door has no bottom guide



CORRECTION: Recommend full replacement of the door
Door size 25 1/2 inches x 73 inches
Need wall mount bottom door guide
To replace the door will require the removal of the top decor trim
Unlocking the roller locks and removing the door
Installing bottom door guide
Installing door lock on the door
Installing and locking the door back to the rollers and adjusting for proper closing and opening.
Reinstalling decor trim
Requesting 1 hour

Labor

Job #	Description	Total
9	DOOR	N/C

Subtotal for Job #9: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 15 Dec 2025

Customer Signature : _____

