



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72592  
 Promised Date:  
 17 FEB 26



WO #: 72592 (Appointment Date: 23 OCT 2025 - Time: 08:15am)  
 Customer Name: 59783 - ERIVES, JAVIER  
 Completed Date: 12 FEB 26  
 Invoice#: Author: BRIAN  
 Stock Desc: 9524 2025 OPEN RANGE 26BHS  
 Serial#: 58TBM0BPXS75L3261 Date In: 23 OCT 25  
 Chassis#: 58TBM0BPXS75L3261 Time In:  
 Miles/Hrs:  
 Tag#: 6873  
 Purchased Date: 02 MAY 25  
 Warranty Date: 02 MAY 25

**Job #0 - Warranty**  
 CLAIM: J01503060

**Subtotal for Job #0: 0.00**

**Job #1 - Warranty**  
 COMPLAINT: CUSTOMER STATES THE VENT HOOD LATCH HAS BROKEN

CAUSE: Latch on range vent is broken.  
 CORRECTION: Replace range vent with new one.  
 Replaced vent cover  
 .30hrs

**Labor**

Job #	Description	Total
1	EXTERIOR RANGE VENT	53.70

**Parts**

Part #	Description	Qty	Price	Total
2052391	VENT, RANGEHOOD OUTSIDE BLACK ABS	1.00	12.12	12.12

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

**Subtotal for Job #1: 65.82**

**Job #2 - Warranty**  
 COMPLAINT: CUSTOMER STATES RANGE HOOD LIGHT HAS COME DISCONNECTED

CAUSE: Wire from hood LED light has been pulled out.  
 CORRECTION: Replace hood LED light.  
 Replaced light.  
 .20hrs

**Labor**

Job #	Description	Total
2	RANGE VENT LIGHT	35.80

Customer #: 59783  
 ERIVES, JAVIER



<b>Parts</b>				
Part #	Description	Qty	Price	Total
2065685	LIGHT, LED RANGEHOOD INVISION	1.00	12.58	12.58
<b>Subtotal for Job #2:</b>				<b>48.38</b>

**Job #3 - Warranty**

COMPLAINT: CUSTOMER STATES FURNACE WILL NOT LIGHT

CAUSE: Checked wires at furnace and when thermostat wires are connected together furnace works fine. Wall thermostat is faulty.  
 Faulty thermostat

CORRECTION: Remove and replace thermostat.

New thermostat arrived  
 Plugged the unit into shore power , opened the slide room  
 Removed thermostat from the wall plate, unscrewed the wall plate , disconnected the old thermostat by unclipping the each wire  
 Connected the new thermostat, turn on the propane  
 Tested the air conditioner and fan settings, turned the thermostat to heat and the furnace would not turn on.  
 Removed the cover from the air conditioner eroded each of the wire connectors to ensure the colors match from the ac control board to the thermostat which they did.  
 Removed the access panel to the furnace and checked wiring connections  
 Found the red and white wires were reversed .  
 Switched he wires and the furnace turned on.  
 Found the fan would run constantly but the burner would only run for about 3 seconds and turn off then relight and would do this constantly. Connected the thermostat wires together at the thermostat and the furnace come on and the burner would stay on . Checked the line pressure on the propane which was low at 10 WC, adjusted to 11  
 Started a new diagnostic job line  
 Contacted colemack incident number 145776  
 Was told to check the voltage between red and blue which was 13.1  
 Checked the voltage between white and blue was 11.64  
 Was asked what the tag number was listed on the new thermostat was 9420-381  
 I was told this was the old thermostat the number should be 9420A381  
 Was asked where this came from and the shipping label was from Jayco  
 Was told they would be sending a new thermostat which should arrive within 7 days.  
 Closed the unit up waiting on parts  
 Since the thermostat sent was not the correct one will request 1 hour to change out again and retest furnace.

<b>Labor</b>		
Job #	Description	Total
3	MULTIPLE LABOR CODES	179.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
17303	THERMOSTAT WIRE 18/7 BROWN	1.00	0.55	0.55
2068869	THERMOSTAT, ANALOG HEAT/COOL 12V BLACK - COLEMAN	1.00	43.76	43.76
<b>Subtotal for Job #3:</b>				<b>223.31</b>

**Job #WIN-STD - Internal**

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize unit.

CORRECTION: Winterized unit.

<b>Labor</b>		
Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

<b>Parts</b>				
--------------	--	--	--	--



Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	2.00	N/C	N/C

**Subtotal for Job #WIN-STD: 0.00**

Parts Total:	69.01
Labour Total:	268.50
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>337.51</b>

NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : \_\_\_\_\_

Date: 12 Feb 2026

W/O: 72592  
Promised Date: 17 FEB 26



Customer Order

Customer #: 59783  
ERIVES, JAVIER

