

Claim statement

Claim	J01489566	Unit	58TBM0BK5S75C3107		
Dealer account #:	296921	Chassis:	0001452272		
	MYERS RV CENTER, INC	Description;	20FBS OPEN RANGE TT		
Reference:		Registration date:	01/06/2026		
		Mileage:			
Customer:	Torres, Christopher	Create date:	01/05/2026	Start date	01/23/2026
Repair line	J01489566-001	Status:	Confirmed	End date	01/23/2026
Claim type	Standard	Status date	01/28/2026	Rep line desc:	Fenderskirt
Claim group	WarrClaim			Pre auth#:	PA001309394
yutzya January 7, 2026 1:20 PM Jayco P#0321158 yutzya January 7, 2026 1:19 PM approve .2 to replace					

Complaint: Passenger side fender skirt is cracked

Cause: Crkd Found that the screws were too tight

Correction: Replace fenderskirt

Transaction type	Main Op.	Operation no	Item number	Disp. code	Adj. Reason Code	Description	Req. qty	Unit	Unit price	Req. amount	Approved quantity	Approved amount
Labor	Yes	0301005C				FENDERSKIRT-REPLACE-TOWABIZ	0.20		\$179.00	\$35.80	0.20	\$35.80
Item	No		0321158	PHOTOA		FENDERSKIRT,66.13X9.50 BLK HDPE	1.00	EA	\$50.29	\$50.29	1.00	\$50.29
Charges	No					Parts markup	1.00		\$15.09	\$15.09	1.00	\$15.09

	Labor	Parts	Charges	Total		
Total requested amount	\$35.80	\$50.29	\$15.09	\$101.18	Invoice status	Invoiced
Total adjusted	\$0.00	\$0.00	\$0.00	\$0.00	Invoiced date	1/28/2026
Total approved amount	\$35.80	\$50.29	\$15.09	\$101.18	Payment reference	456119

Claim total J01489566	Labor	Parts	Charges	Total
Total requested amount	\$35.80	\$50.29	\$15.09	\$101.18
Total adjusted	\$0.00	\$0.00	\$0.00	\$0.00
Total approved amount	\$35.80	\$50.29	\$15.09	\$101.18