



12024 Central Ave SE ★ Albuquerque NM 87123  
 www.MYERSRV.com  
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72056  
 Promised Date:  
 01 FEB 26



WO #: 72056  
 Customer Name: 1000 - MYERS "RV"  
 CENTER, INC.

Completed Date: 19 FEB 26  
 Invoice#:  
 Author: ADVISOR  
 Stock Desc: 9575 2026 SANIBEL  
 38LAUNDRY  
 Serial#: 706104  
 Chassis#: 5ZT3SN3B7TG706104  
 Miles/Hrs:  
 Tag#:  
 Purchased Date:  
 Warranty Date:

Date In: 19 JUL 25  
 Time In:

**Job #1 - Internal**

COMPLAINT: CHECK IN NEW UNIT

CAUSE: Diag

CORRECTION: Completed

**Labor**

Job #	Description	Total
1	DIAGNOSIS	N/C
<b>Subtotal for Job #1:</b>		<b>0.00</b>

**Job #2 - Warranty**

COMPLAINT: Outside plug missing cover.

CAUSE: Outside plug is missing cover  
 Missing

CORRECTION: Replace outside plug part on order.  
 Installed

**Labor**

Job #	Description	Total
2	MULTIPLE LABOR CODES	38.00

**Parts**

Part #	Description	Qty	Price	Total
14357	COVER, GFI, EXTERIOR, HORIZONTAL, BLACK - 3" X 4-3/4"	1.00	5.60	5.60

**Subtotal for Job #2: 43.60**

**Job #3 - Warranty**

COMPLAINT: Trim in Multiple areas is loose.

CAUSE: Loose trim in several areas.

CORRECTION: Re-stapled all loose trim. .20

Customer #: 1000  
 MYERS "RV" CENTER,  
 INC.,





<b>Labor</b>		
Job #	Description	Total
3	TRIM	38.00
<b>Subtotal for Job #3:</b>		<b>38.00</b>

**Job #4 - Warranty**

COMPLAINT: Kitchen cabinet doors are coming apart.

CAUSE: Cabinet door under kitchen sink are coming apart. See pictures  
 Replace

CORRECTION: Remove and replace with new doors. Parts on order.  
 Completed

<b>Labor</b>		
Job #	Description	Total
4	MULTIPLE LABOR CODES	152.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
20-1862	DOOR STOP BUMPER - SET OF 2	1.00	4.27	4.27
F100726264	DOOR, CABINET ANDOVER MALT 12" X 24"	2.00	44.34	88.68

<b>Other Services</b>				
Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	19.70	19.70
<b>Subtotal for Job #4:</b>				<b>264.65</b>

**Job #5 - Warranty**

COMPLAINT: Dump handles under coach are missing.

CAUSE: Dump tank handles are missing in several locations  
 Missing

CORRECTION: Replace handles.Parts on order  
 Installed

<b>Labor</b>		
Job #	Description	Total
5	MULTIPLE LABOR CODES	9.50

<b>Parts</b>				
Part #	Description	Qty	Price	Total
60P14615A	HANDLE, T1006-6N, BLACK, 19462	2.00	0.69	1.38
60P15611A	T-HANDLE FOR WASTEGATE VALVE - GRAY	2.00	0.84	1.68

**Subtotal for Job #5: 12.56**

**Job #6 - Warranty**

COMPLAINT: Bedroom dresser top is damaged hole for tv plug is peeling finish off.

CAUSE: Top of bedroom dresser is damaged.see pictures.  
 Replace

CORRECTION: Remove damaged top,and replace with new piece. Partnon order.  
 Completed

<b>Labor</b>		
Job #	Description	Total
6	MULTIPLE LABOR CODES	190.00





**Parts**

Part #	Description	Qty	Price	Total
F100748616	TOP, DRESSER, SLIDE OUT 18-3/4" X 72-1/2" BRAEMAR ESPRESSO	1.00	159.92	159.92

**Other Services**

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	143.91	143.91

**Subtotal for Job #6: 493.83**

**Job #PDI1 - Internal**

COMPLAINT: Transferred to RV\*72548 on 17 OCT 25  
 Estimate amount was 0.00  
 PRE-PDI NEW TT - 3.0

CAUSE: PDI Needed

CORRECTION: PDI Completed

**Labor**

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

**Subtotal for Job #PDI1: 0.00**

**Job #WIN-DLX - Internal**

COMPLAINT: Transferred to RV\*72548 on 17 OCT 25  
 Estimate amount was 0.00  
 WINTERIZE INCLUDE W/D, ICEMAKER

CAUSE: Winterize unit

CORRECTION: Winterized unit.

**Labor**

Job #	Description	Total
WIN-DLX	WINTERIZE RV - DELUXE CLASS A	N/C

**Subtotal for Job #WIN-DLX: 0.00**

Parts Total: 261.53  
 Labour Total: 427.50  
 Sublet Total: 0.00  
 Extras Total: 163.61  
**WORK ORDER TOTAL: 852.64**



NOTICE:  
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

\*\*MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND\*\*

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 19 Feb 2026

Customer Signature : \_\_\_\_\_

Customer Work Order

W/O: 72056  
Promised Date: 21 FEB 26



Customer #: 1000  
MYERS "RV" CENTER,  
INC.,

