

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 2488267 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT3SN3B7TG706104 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 049 / 049A <b>ITEM #</b> SNF38LAUNDRY <b>DEALER RO #</b> 72056 <b>CLAIM START DATE</b> 11/03/2025 <b>CLAIM END DATE</b> 01/01/1900
--	---

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**      **Operation Code** 40-197-01-11-001322      **Operational Description**  
 Exterior GFI Recept Cover - Including Gasket - Electrical/110 Volt Exterior/  
 Replace/Electrical

**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-11-03 15:01:41 :: Outside plug missing cover. / Outside plug is  
 missing cover / Replace outside plug.part on order. Additional Note : ryliefayth@gmail.com, 2025-11-03  
 15:11:36 :: Need auth to order parts

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b> \$38.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b> \$38.00

**Notes**

### Labor

**Line# 2**      **Operation Code** 30-102-12-00-001096      **Operational Description**  
 Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/  
 Resecure or Tighten/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-11-03 15:12:26 :: Trim in Multiple areas is loose. / Loose trim in  
 several areas./ Re-stapled all loose trim.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b> \$38.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b> \$38.00

**Notes**  
 NVCB .20 to secure the loose trim. Per dealers description of this repair. This authorization is  
 pending ALL requirements of repair code have been met. Dp

### Labor

**Line# 3**      **Operation Code** 30-100-01-00-001035      **Operational Description**  
 Cabinet Door - Interior/Cabinetry/Replace/No Tread Code

**Complaint, Cause, Correction**  
 Original Note : ryliefayth@gmail.com, 2025-11-03 15:18:34 :: Kitchen cabinet doors are coming apart. / Cabinet  
 door under kitchen sink are coming apart. See pictures / Remove and replace with new doors. Additional Note :  
 ryliefayth@gmail.com, 2025-11-03 15:20:53 :: Need auth to order parts. REQUESTED .80 BECAUSE 2 DOORS WILL  
 BE REPLACED.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.80	<b>Sub Labor Amt</b> \$152.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.40	<b>Appr Labor Amt</b> \$76.00

**Notes**  
 The time requested is excessive for this repair, time adjusted. VCB .40 to R&R the cabinet door  
 due to it seperating. Per dealers description of this repair. This authorization is pending ALL  
 requirements of repair code have been met. Dp

### Labor

**Line# 4**      **Operation Code**      **Operational Description**

60-138-01-00-001525 Termination Valve Handle - Plumbing/Drainage System/Replace/No Tread Code

**Complaint, Cause, Correction**

Original Note : ryliefayth@gmail.com, 2025-11-03 15:22:51 :: Dump handles under coach are missing. / Dump tank handles are missing in several locations / Replace handles.Parts on order Additional Note : ryliefayth@gmail.com, 2025-11-03 15:27:14 :: Need auth to order part.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.05	<b>Sub Labor Amt</b>	\$9.50
<b>Serial#</b>	<b>Appr Hrs</b>	0.05	<b>Appr Labor Amt</b>	\$9.50

**Notes**

NVCB .05 to replace missing pull handles. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

**Labor Line# 5**

**Operation Code**

30-100-01-00-001059

**Operational Description**

Entertainment Center Countertop - Interior/Cabinetry/Replace/No Tread Code

**Complaint, Cause, Correction**

Original Note : ryliefayth@gmail.com, 2025-11-03 15:26:57 :: Bedroom dresser top is damaged hole for tv plug is peeling finish off. / Top of bedroom dresser is damaged.see pictures. / Remove damaged top,and replace with new piece. Part on order. Additional Note : ryliefayth@gmail.com, 2025-11-03 15:27:09 :: Need auth to order part.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	1.00	<b>Sub Labor Amt</b>	\$190.00
<b>Serial#</b>	<b>Appr Hrs</b>	1.00	<b>Appr Labor Amt</b>	\$190.00

**Notes**

NVCB 1.00 to R&R the dresser top due to it being chipped. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

---

**Submitted**

Labor Amt	\$427.50
Parts & Freight	\$0.00
<b>Total</b>	<b>\$427.50</b>

**Approved**

Labor Amt	\$351.50
Parts & Freight	\$0.00
<b>Total</b>	<b>\$351.50</b>

---

**DEALER**

**DATE**

**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER**

**DATE**

**SIGNATURE**

All repairs described have been inspected and are satisfactory.