

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2488267
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT3SN3B7TG706104
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	049 / 049A
OWNER INFORMATION		ITEM #	SNF38LAUNDRY
		DEALER RO #	72056
		CLAIM START DATE	11/03/2025
		CLAIM END DATE	02/19/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code	Operational Description	
	40-197-01-11-001322	Exterior GFI Recept Cover - Including Gasket - Electrical/110 Volt Exterior/Replace/Electrical	
	Complaint, Cause, Correction Original Note : ryliefayth@gmail.com, 2025-11-03 15:01:41 :: Outside plug missing cover. / Outside plug is missing cover / Replace outside plug.part on order. Additional Note : ryliefayth@gmail.com, 2025-11-03 15:11:36 :: Need auth to order parts		
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00
Notes			

Line# 1	Item #		Description			
	USERPART		14357 Cover, GFI, exterior, horizontal, Black 3" x 4 3/4"			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$5.60	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$5.60	Appr Freight	\$0.00
	Notes					

Line# 2	Operation Code 30-102-12-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction Original Note : ryliefayth@gmail.com, 2025-11-03 15:12:26 :: Trim in Multiple areas is loose. / Loose trim in several areas./ Re-stapled all loose trim.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
	Notes NVCB .20 to secure the loose trim. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp			

Line# 1	Item #	Description				
	USERPART	Staples				
	Model #	Serial #			Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$1.90	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$1.90	Appr Freight	\$0.00

Notes

Labor

Line# 3

Operation Code

30-100-01-00-001035

Operational Description

Cabinet Door - Interior/Cabinetry/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : ryliefayth@gmail.com, 2025-11-03 15:18:34 :: Kitchen cabinet doors are coming apart. / Cabinet door under kitchen sink are coming apart. See pictures / Remove and replace with new doors. Additional Note : ryliefayth@gmail.com, 2025-11-03 15:20:53 :: Need auth to order parts. REQUESTED .80 BECAUSE 2 DOORS WILL BE REPLACED.

Model#

Dlr Sub Hrs

0.80

Sub Labor Amt \$152.00

Serial#

Appr Hrs

0.80

Appr Labor Amt \$152.00

Notes

The time requested is excessive for this repair, time adjusted. VCB .40 to R&R the cabinet door due to it seperating. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Dp.

VCB .80 to R&R 2 cabinet doors due to them seperating. Per dealers description of this repair.

This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1

Item

F100726264

Description

DOOR, CABINET, 12" X 24", ANDOVER MALT, 761089

Model

Serial

Part tag

Sub Qty

2.00

Sub Dlr Price

\$88.69

Sub Freight

\$19.70

Appr Qty

2.00

Appr Dlr Price

\$88.69

Appr Freight

\$19.70

Notes

Line# 2

Item

USERPART

Description

20-1862 Door stop bumper set of 2

Model

Serial

Part tag

Sub Qty

1.00

Sub Dlr Price

\$4.27

Sub Freight

\$0.00

Appr Qty

1.00

Appr Dlr Price

\$4.27

Appr Freight

\$0.00

Notes

Labor

Line# 4

Operation Code

60-138-01-00-001525

Operational Description

Termination Valve Handle - Plumbing/Drainage System/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : ryliefayth@gmail.com, 2025-11-03 15:22:51 :: Dump handles under coach are missing. / Dump tank handles are missing in several locations / Replace handles.Parts on order Additional Note : ryliefayth@gmail.com, 2025-11-03 15:27:14 :: Need auth to order part.

Model#

Dlr Sub Hrs

0.05

Sub Labor Amt \$9.50

Serial#

Appr Hrs

0.05

Appr Labor Amt \$9.50

Notes

NVCB .05 to replace missing pull handles. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

Part

Line# 1

Item

60P14615A

Description

HANDLE, T1003-6N, BLACK, 19462 HANDLE, T1003-6N, BLACK, 19462

Model

Serial

Part tag

Sub Qty

2.00

Sub Dlr Price

\$1.59

Sub Freight

\$0.00

Appr Qty

2.00

Appr Dlr Price

\$1.36

Appr Freight

\$0.00

Notes

Computer rounded down \$0.02

Line# 2

Item

60P15611A

Description

T-HANDLES FOR WASTEGATE VALVE GRAY, 34054 T-HANDLES FOR WASTEGATE VALVE GRAY, T1003-6GN-0, 34054

Model #		Serial #		Part tag	
Sub Qty	2.00	Sub Dlr Price	\$1.93	Sub Freight	\$0.00
Appr Qty	2.00	Appr Dlr Price	\$1.68	Appr Freight	\$0.00

Notes

Labor

Line# 5 **Operation Code** **Operational Description**
30-100-01-00-001059 Entertainment Center Countertop - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : ryliefayth@gmail.com, 2025-11-03 15:26:57 :: Bedroom dresser top is damaged hole for tv plug is peeling finish off. / Top of bedroom dresser is damaged.see pictures. / Remove damaged top,and replace with new piece. Part on order. Additional Note : ryliefayth@gmail.com, 2025-11-03 15:27:09 :: Need auth to order part.

Model#	Dlr Sub Hrs	1.00	Sub Labor Amt	\$190.00
Serial#	Appr Hrs	1.00	Appr Labor Amt	\$190.00

Notes
NVCB 1.00 to R&R the dresser top due to it being chipped. Per dealers description of this repair.
This authorization is pending ALL requirements of repair code have been met. Dp

Part

Line# 1 **Item #** **Description**
F100748616 TOP, DRESSER, SLIDE OUT, 18-3/4" X 72-1/2", BRAEMAR ESPRESSO, PRINT# 12-005215D, 7202347

Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$159.92	Sub Freight	\$143.91
Appr Qty	1.00	Appr Dlr Price	\$159.92	Appr Freight	\$143.91

Notes

Submitted			Approved		
	Labor Amt	\$427.50		Labor Amt	\$427.50
	Parts & Freight	\$427.05		Parts & Freight	\$427.03
	Total	\$854.55		Total	\$854.53

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.