

This authorization is pending ALL requirements of repair code have been met. Dp.

Labor

Line# 4

Operation Code **Operational Description**
60-138-01-00-001525 Termination Valve Handle - Plumbing/Drainage System/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : ryliefayth@gmail.com, 2025-11-03 15:22:51 :: Dump handles under coach are missing. / Dump tank handles are missing in several locations / Replace handles.Parts on order Additional Note : ryliefayth@gmail.com, 2025-11-03 15:27:14 :: Need auth to order part.

Model# **Dlr Sub Hrs** 0.05 **Sub Labor Amt** \$9.50
Serial# **Appr Hrs** 0.05 **Appr Labor Amt** \$9.50

Notes

NVCB .05 to replace missing pull handles. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

Labor

Line# 5

Operation Code **Operational Description**
30-100-01-00-001059 Entertainment Center Countertop - Interior/Cabinetry/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : ryliefayth@gmail.com, 2025-11-03 15:26:57 :: Bedroom dresser top is damaged hole for tv plug is peeling finish off. / Top of bedroom dresser is damaged.see pictures. / Remove damaged top,and replace with new piece. Part on order. Additional Note : ryliefayth@gmail.com, 2025-11-03 15:27:09 :: Need auth to order part.

Model# **Dlr Sub Hrs** 1.00 **Sub Labor Amt** \$190.00
Serial# **Appr Hrs** 1.00 **Appr Labor Amt** \$190.00

Notes

NVCB 1.00 to R&R the dresser top due to it being chipped. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

Submitted		Approved	
Labor Amt	\$427.50	Labor Amt	\$427.50
Parts & Freight	\$0.00	Parts & Freight	\$0.00
Total	\$427.50	Total	\$427.50

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.