



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72579-1
 Promised Date:
 12 FEB 26



WO #: 72579-1

Customer Name: 61018 - RICE, DANIEL RICHARD
 Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9629 2026 AVENGER 16BHX
 Serial#: 5ZT2AVEC5TG815374
 Chassis#: 5ZT2AVEC5TG815374
 Miles/Hrs:
 Tag#: 7042
 Purchased Date: 02 JAN 26
 Warranty Date: 02 JAN 26

Date In: 02 JAN 26
 Time In:

Job #2 - Warranty

COMPLAINT: Rear decals peeling on driver side

CAUSE: Decals drivers side rear bubbled and cracked
 Decals drivers side upper front bubbled and cracked
 Decals passenger side upper front bubbled and cracked
 Decals passenger side rear bubbled and cracked

CORRECTION: Driver side rear decals - had to use a heat gun to remove the large decal, Used a cleaner to to remove all old adhesive. Removed silicone on the corner molding in this area. Cut the new decal to fit and installed new decal. Resealed the corner mold with silicone.

Drivers side upper front - had to use a heat gun to remove old decal. Used cleaner to remove adhesive. Removed the silicone from the decal areas. Started with the gold decal lined up in place and installed new over 3 different surfaces. Next was the black strip decal. Lined up in place and installed it over three surfaces. Resealed the decal area with silicone

Passenger side front upper decals - Again had to use a heat gun to remove the two old decals. Removed the silicone from the front corner in the decal area. Cleaned the adhesive from the side of the unit. Started with the gold decal lined it and installed. Next the black decal lined it up and installed it. Both decals installed over 3 surfaces. Resealed the corner molding with silicone

Passenger side rear - Had to use a heat gun to remove the decal. Used cleaner to remove all old adhesive. Removed silicone from the corner mold in the decal area. Lined up the decal and installed it. Resealed corner mold with silicone.
 Work completed

Labor

Job #	Description	Total
2	MISC LABOUR CODE (INTERNAL)	1,140.00

Parts

Part #	Description	Qty	Price	Total
F100731272	GRAPHIC, DC # 1 LH AVENGER 2026 (171012)	1.00	5.46	5.46
F100731340	GRAPHIC, DC # 2 LH AVENGER 2026 (171017)	1.00	4.65	4.65

Customer #: 61018
 RICE, DANIEL RICHARD



W/O: 72579-1
Promised Date: 13 FEB 26

F100731342	GRAPHIC, DC # 3 LH AVENGER 2026 (171016)	1.00	2.96	2.96
F100731344	GRAPHIC, DC # 4 LH AVENGER 2026 (171018)	1.00	11.20	11.20
F100731274	GRAPHIC, DC # 1 RH AVENGER 2026 (171013)	1.00	5.46	5.46
F100731341	GRAPHIC, DC # 2 RH AVENGER 2026 (171015)	1.00	4.65	4.65
F100731343	GRAPHIC, DC # 3 RH AVENGER 2026 (171017)	1.00	2.96	2.96
F100731370	GRAPHIC, DC # 4 RH AVENGER 2026 (171019)	1.00	11.20	11.20
5302	SILICONE CAULK SEALANT - BLACK	1.00	11.13	11.13

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	45.24	45.24

Subtotal for Job #2: 1,244.91

Parts Total: 59.67
Labour Total: 1,140.00
Sublet Total: 0.00
Extras Total: 45.24

WORK ORDER TOTAL: 1,244.91

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 17 Feb 2026

Customer Signature : _____



Customer #: 61018
RICE, DANIEL RICHARD

