

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Authorized
MYERS RV CENTER INC		CLAIM	2532176
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVEC5TG815374
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	452 / 452
OWNER INFORMATION		ITEM #	AVT16BHX-452
DANIEL RICE		DEALER RO #	72579
10413 MANZANILLO AVE NE		CLAIM START DATE	12/18/2025
Albuquerque, NM 87111		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	01/02/2026	WARRANTY EXPIRATION DATE	01/02/2027

Claim Line Details

Labor

Line# 1

Operation Code	20-43-01-00-000589	Operational Description
		Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:23:48 :: Complaint: Rear decals are peeling on the driver side Cause: Adhesion failure Correction: Order and replace decals		
Model#	Dlr Sub Hrs	Sub Labor Amt
	1.00	\$190.00
Serial#	Appr Hrs	Appr Labor Amt
	1.00	\$190.00
Notes		
NVCB,R&R decals,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD		

Labor

Line# 2

Operation Code	70-167-01-00-001984	Operational Description
		Gas Control Valve - Electronic Ignition - Appliances/Water Heater (Suburban)/ Replace/No Tread Code
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2025-12-18 17:26:13 :: Complaint: Water heater will not raise water temp past 96 degrees Cause: Spoke with Samantha at Suburban, tested board wiring at pin terminals with voltmeter. Gas valve is bad. Correction: Replace gas valve as advised by Samantha at Suburban. She stated her name should be enough and we would not need an authorization/case number.		
Model#	Dlr Sub Hrs	Sub Labor Amt
ST42	2.00	\$380.00
Serial#	Appr Hrs	Appr Labor Amt
251703106t	1.00	\$190.00
Notes		
Forest River is currently reviewing your request with the Vendor. Please verify your shipping address, please acknowledge, placing the claim back on our side. We will update the line once we receive their response. Thank you.TD		
Address is 12024 Central Ave. SE, Albuquerque, NM 87123		
VCB,Suburban will authorize the replacement of the Gas Valve, field scrap the old part, warranty allowance time is 1.0 hrs.TD		

Labor

Line# 3

Operation Code	10-3-01-20-000073	Operational Description
		Wheel Center Cap - Frame & Chassis/Wheels, Tires, Hubcaps/Replace/Wheels
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2026-01-14 11:04:51 :: Complaint: Passenger tire is missing the dust cap Cause: Dust cap missing Correction: Replace dust cap		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.05	\$9.50
Serial#	Appr Hrs	Appr Labor Amt
	0.05	\$9.50

Notes

**Labor
Line# 4**

Operation Code
20-43-01-00-000589

Operational Description
Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No
Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-06 10:18:49 :: This is related to line 1. There are a total of 6 decals needing replacement, at the time of authorization, we only asked for 1.0 hour, but with 6 decals needing to be replaced, our labor time is going to increase quite a bit.

Model#	Dlr Sub Hrs	5.00	Sub Labor Amt	\$950.00
Serial#	Appr Hrs	5.00	Appr Labor Amt	\$950.00

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Submitted	Labor Amt	\$1,529.50	Approved	Labor Amt	\$1,339.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$1,529.50		Total	\$1,339.50

DEALER _____ **DATE** _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
All repairs described have been inspected and are satisfactory.