



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72585
 Promised Date:
 24 OCT 25



WO #: 72585
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9634 2026 TRACER 275BH
 Serial#: 526582
 Chassis#: 5ZT2TRTB1TB526582
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 22 OCT 25
 Time In:

Job #1 - Internal
 CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #PDI1 - Internal
 COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Pdi travel trailer

CORRECTION: Pdi travel trailer
 Complete

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	10.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal
 COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize basic

CORRECTION: Complete

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,





Labor				
Job #	Description			Total
WIN-STD	WINTERIZE RV - BASIC			N/C

Parts				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Job #2 - Internal

COMPLAINT: Body damage rear bottom corner of slide

CAUSE: Rub mark on bottom rear corner of the slide out

CORRECTION: During the pdi found a rub mark on the bottom rear corner of the slide
Further inspection found it was a rub or scrap from something plastic
Used adhesive remover and buff the rub off
Doesnt appear to be damaged and no visible marks

Labor				
Job #	Description			Total
2	DIAGNOSIS			N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: Panel in passenger side compartment coming off

CAUSE: Loose panel in front compartment

CORRECTION: Found the panel on the passenger side compartment loose during the pdi
Nailed the panel back in place
Work completed
.20HRS

Labor				
Job #	Description			Total
3	PANEL			N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Putty clean up though out unit

CAUSE: Excessive putty though out

CORRECTION: Cleaned up excessive putty though out unit ceiling and walls
Reset raised staples
Work completed
.50HRS

Labor				
Job #	Description			Total
4	TOUCH UP			N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: Bathroom door is hitting the door jam and has damage on bottom

CAUSE: Bathroom door rubbing on the door jam

CORRECTION: Found the bathroom door was rubbing on the door jam top middle and bottom and had
rubbed the bottom corner down to the bare wood



Found the hinges were all bent
 Removed each hinge straightened the, and reattached
 The door stopped rubbing on the door jam
 Used stain touch up on the bottom of the door to cover up the rub marks
 Work completed
 .50HRS

Labor		
Job #	Description	Total
5	BATHROOM DOOR	N/C
Subtotal for Job #5:		0.00

Job #6 - Warranty

COMPLAINT: Water leak city water connection inside compartment

CAUSE: Loose connector in the wall

CORRECTION: Found the city water connection was leaking on the inside of the storage compartment during the pre pdi.

Removed the 3 screws on the out side of the unit pull the connection out

Connected water to the city water hook up

Found the connector in the wall was loose

Tightened the fitting retested with city water the fitting was no longer leaking

Disconnected the water hose screwed the city water connection back to the side of the unit

.30HRS

Labor		
Job #	Description	Total
6	WATER LEAK	N/C
Subtotal for Job #6:		0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 13 Jan 2026

