



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72585
 Promised Date:
 24 OCT 25



WO #: 72585
 Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 14 JAN 26
 Invoice#:
 Author: BRIAN
 Stock Desc: 9634 2026 TRACER 275BH
 Serial#: 526582
 Chassis#: 5ZT2TRTB1TB526582
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 22 OCT 25
 Time In:

Job #1 - Internal
 CHECK IN NEW UNIT

| Labor | | | Total |
|-------|-------------|--|-------|
| Job # | Description | | |
| 1 | DIAGNOSIS | | N/C |

| Other Services | | | | |
|-----------------------------|--------------------------|------|-------|-------------|
| Code | Description | Qty | Price | Total |
| SS-I | SHOP SUPPLIES - INTERNAL | 1.00 | N/C | N/C |
| Subtotal for Job #1: | | | | 0.00 |

Job #2 - Internal
 COMPLAINT: Body damage rear bottom corner of slide

CAUSE: Rub mark on bottom rear corner of the slide out

CORRECTION: During the pdi found a rub mark on the bottom rear corner of the slide
 Further inspection found it was a rub or scrap from something plastic
 Used adhesive remover and buff the rub off
 Doesnt appear to be damaged and no visible marks

| Labor | | | Total |
|-------|-------------|--|-------|
| Job # | Description | | |
| 2 | DIAGNOSIS | | N/C |

Subtotal for Job #2: 0.00

Job #3 - Warranty
 COMPLAINT: Panel in passenger side compartment coming off

CAUSE: Loose panel in front compartment

CORRECTION: Found the panel on the passenger side compartment loose during the pdi
 Nailed the panel back in place
 Work completed
 .20HRS

| Labor | | | Total |
|-------|-------------|--|-------|
| Job # | Description | | |
| 3 | PANEL | | 38.00 |

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #3: 38.00

Job #4 - Warranty

COMPLAINT: Putty clean up though out unit

CAUSE: Excessive putty though out

CORRECTION: Cleaned up excessive putty though out unit ceiling and walls

Reset raised staples

Work completed

.50HRS

Labor

| Job # | Description | Total |
|-------|-------------|-------|
| 4 | TOUCH UP | 95.00 |

Subtotal for Job #4: 95.00

Job #5 - Warranty

COMPLAINT: Bathroom door is hitting the door jam and has damage on bottom

CAUSE: Bathroom door rubbing on the door jam

CORRECTION: Found the bathroom door was rubbing on the door jam top middle and bottom and had rubbed the bottom corner down to the bare wood

Found the hinges were all bent

Removed each hinge straightened the, and reattached

The door stopped rubbing on the door jam

Used stain touch up on the bottom of the door to cover up the rub marks

Work completed

.50HRS

Labor

| Job # | Description | Total |
|-------|---------------|-------|
| 5 | BATHROOM DOOR | 57.00 |

Subtotal for Job #5: 57.00

Job #6 - Warranty

COMPLAINT: Water leak city water connection inside compartment

CAUSE: Loose connector in the wall

CORRECTION: Found the city water connection was leaking on the inside of the storage compartment during the pre pdi.

Removed the 3 screws on the out side of the unit pull the connection out

Connected water to the city water hook up

Found the connector in the wall was loose

Tightened the fitting retested with city water the fitting was no longer leaking

Disconnected the water hose screwed the city water connection back to the side of the unit

.30HRS

Labor

| Job # | Description | Total |
|-------|-------------|-------|
| 6 | WATER LEAK | 57.00 |

Subtotal for Job #6: 57.00

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Pdi travel trailer

CORRECTION: Pdi travel trailer

W/O: 72585
Promised Date: 31 OCT 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,





Complete

| Labor | | |
|-------|--------------------|-------|
| Job # | Description | Total |
| PDI1 | PDI TRAVEL TRAILER | N/C |

| Parts | | | | |
|--------|-------------|-------|-------|-------|
| Part # | Description | Qty | Price | Total |
| 1000 | L.P. GAS | 10.00 | N/C | N/C |

| Other Services | | | | |
|----------------|---------------|------|-------|-------|
| Code | Description | Qty | Price | Total |
| SS | SHOP SUPPLIES | 1.00 | N/C | N/C |

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal
 COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize basic

CORRECTION: Complete

| Labor | | |
|---------|----------------------|-------|
| Job # | Description | Total |
| WIN-STD | WINTERIZE RV - BASIC | N/C |

| Parts | | | | |
|--------|-------------|------|-------|-------|
| Part # | Description | Qty | Price | Total |
| 21622 | ANTIFREEZE | 3.00 | N/C | N/C |

Subtotal for Job #WIN-STD: 0.00

Parts Total: 0.00
 Labour Total: 247.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 247.00

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 14 Jan 2026

Customer Signature : _____

