

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2550395
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2TRTB1TB526582
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 048 / 048B
 ITEM # TRT275BH
 DEALER RO # 72585
 CLAIM START DATE 01/14/2026
 CLAIM END DATE 02/02/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-102-12-00-002691 Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:19:08 :: Complaint: Panel in passenger side compartment is coming off Cause: Loose panel in front compartment Correction: Nailed the panel back in place

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

Part

Line# 1	Item #	Description			
	USERPART	Nails			
	Model #	Serial #		Part tag	
	Sub Qty	Sub Dlr Price	\$1.90	Sub Freight	\$0.00
	Appr Qty	Appr Dlr Price	\$1.90	Appr Freight	\$0.00

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-102-24-00-003061 Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:21:46 :: Complaint: Putty clean throughout unit Cause: Excessive putty throughout unit Correction: Cleaned up excessive putty throughout unit ceiling and walls, reset raised staples.

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$95.00

Notes

NVCB .50 to remove the excess putty from the entire interior of this unit. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Labor

Line# 3 **Operation Code** **Operational Description**
 30-101-01-00-001073 Hinged Passage Door Hinge, each - Interior/Interior Doors/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-14 10:24:09 :: Complaint: Bathroom door is hitting the door jamb and has damage at the bottom Cause: Bathroom door is rubbing on the door jamb, found hinges were

