



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72661
Promised Date:
06 JAN 26



WO #: 72661 (Appointment Date: 12 NOV 2025 - Time: 08:45am)

Customer Name: 60809 - ANDREWS,
SARAH M

Completed Date: 31 JAN 26

Invoice#: 308372

Author: ADVISOR

Stock Desc: 9420 2025 TRACER
200BHSLE

Serial#: 5ZT2TRJB2SB525510

Chassis#: 5ZT2TRJB2SB525510

Miles/Hrs:

Tag#: 7000

Purchased Date: 19 OCT 25

Warranty Date: 19 OCT 25

Date In: 12 NOV 25

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES LEAK INSIDE UNIT COMING UNDER STOVE AREA - CUST.
BELEIVES IT MAY HAVE SOMETHING TO DO WITH THE CITY WATER CONNECTION SINCE ONLY
LEAKS WHEN USING IT

CAUSE: Found leak at t-connection from outside city receptacle on supply hose.

Replaced hose and tested on city water. Found second leak at quick connect receptacle for rear outside
sprayer. Leak coming from elbow connector. Found pinched cone seal.

CORRECTION: Replaced city water supply hose. Replaced cone seal and crimp ring on outside spray port.
Pressure tested system on city water and pump. No leaks. Completed. Requesting 1.5hr

Labor

Job #	Description	Total
1	WATER LEAK V WATER CONNECTION	256.50

Parts

Part #	Description	Qty	Price	Total
20392	CONE WASHER - QC2 QEST CONE	1.00	0.18	0.18
88-9165	1/2 PLUMB-PEX CLAMP (OETIKER)	1.00	0.51	0.51

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	9.19	9.19

Subtotal for Job #1: 266.38

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES CABINET DOOR, OVER KITCHEN SINK, ON LEFT SIDE THE
FRAME IS CRACKED

CAUSE: Wood split

CORRECTION: Repairs completed as requested by factory. Sanded and covered repair area with seam
tape due to color variations between glue and veneer.

Labor

Job #	Description	Total
2	CABINET DOOR FRAME	380.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------

Customer #: 60809
ANDREWS, SARAH M



8867 ALMOND SILICONE 1.00 11.18 11.18

Subtotal for Job #2: 391.18

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES CABINET DOOR, OVER KITCHEN SINK, ON RIGHT SIDE THE HINGE IS COMING APART

CAUSE: Hardware stripped

CORRECTION: Replaced fasteners and retested. Completed

Labor

Job #	Description	Total
3	CABINET DOOR ADJUST	38.00

Subtotal for Job #3: 38.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES CABINET DOOR OVER DINETTE HAS COME OFF

CAUSE: Hardware failure

CORRECTION: Replaced fasteners and tested. Completed

Labor

Job #	Description	Total
4	CABINET DOOR	38.00

Subtotal for Job #4: 38.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATE FURRION SOUND BAR IS NOT WORKING

CAUSE: Loose connection. Blown fuse

CORRECTION: Removed speaker sound bar and secured molex connection. Replaced fuse. Tested. Completed

Labor

Job #	Description	Total
5	SOUNDBAR DIAGNOSE	57.00

Parts

Part #	Description	Qty	Price	Total
1702	ATC-10 FUSE	1.00	0.30	0.30

Subtotal for Job #5: 57.30

Job #6 - Warranty

COMPLAINT: CUSTOMER STATES, BY TOILET, VENT AT SHOWER AREA HAS DUCTING COMING OUT

CAUSE: Ductwork protrusion

CORRECTION: Removed vent. Trimmed ductwork and reinstalled vent. Completed

Labor

Job #	Description	Total
6	FURNACE DUCTING	76.00

Subtotal for Job #6: 76.00

Job #NOTE - External

COMPLAINT: CUSTOMER HAS ANOTHER OPEN WO#72627
CUSTOMER DOES NOT WANT UNIT WINTERIZE

W/O: 72661
Promised Date: 06 JAN 26



Customer #: 60809
ANDREWS, SARAH M



W/O: 72661
Promised Date: 06 JAN 26



Customer #: 60809
ANDREWS, SARAH M



CAUSE: Diag

CORRECTION: Completed

Labor

Job #	Description	Total
NOTE	DIAGNOSIS	N/C

Subtotal for Job #NOTE: 0.00

Job #WIN-STD - External

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize

CORRECTION: Completed

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Parts Total:	12.17
Labour Total:	845.50
Sublet Total:	0.00
Extras Total:	9.19
WORK ORDER TOTAL:	866.86

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 31 Jan 2026

