



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72754
 Promised Date:
 12 FEB 26



WO #: 72754

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 11 FEB 26
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9648 2026 CRUSADER
 BONUS38
 Serial#: 128475
 Chassis#: 5ZT3CS3B6TG128475
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 22 DEC 25
 Time In:

Job #5W-PRE PDI - Internal

COMPLAINT: 5TH WHEEL PRE PDI 4.0 HRS

CAUSE: Pre

CORRECTION: Completed

Labor

Job #	Description	Total
5W-PRE PDI	MISC LABOUR CODE (INTERNAL)	N/C

Parts

Part #	Description	Qty	Price	Total
1703	ATC-15 FUSE	1.00	N/C	N/C
15420	ALKALINE AA BATTERY	2.00	N/C	N/C
1000	L.P. GAS	5.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #5W-PRE PDI: 0.00

Job #WIN-DLX - Internal

COMPLAINT: WINTERIZE INCLUDE W/D, ICEMAKER

CAUSE: Winterize

CORRECTION: Completed

Labor

Job #	Description	Total
WIN-DLX	WINTERIZE RV - DELUXE CLASS A	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	6.00	N/C	N/C

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #WIN-DLX: 0.00

Job #01 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Passenger side compartment door interior trim detached

CORRECTION: Resecure with sealant and fasteners.

Requesting .3 hr

Completed

Labor

Job #	Description	Total
01	MULTIPLE LABOR CODES	57.00

Subtotal for Job #01: 57.00

Job #02 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Battery vent cover on exterior not attached

CORRECTION: Secure with fasteners

Requesting .2hr

Completed

Labor

Job #	Description	Total
02	MULTIPLE LABOR CODES	38.00

Subtotal for Job #02: 38.00

Job #03 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Driver side compartment strut not attached at front

CORRECTION: Secure strut bracket onto compartment door frame. Test

Requesting.3 hr

Completed

Labor

Job #	Description	Total
03	MULTIPLE LABOR CODES	57.00

Subtotal for Job #03: 57.00

Job #04 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Gray tank dump valve handle missing.

CORRECTION: Replace

Requesting.1 hr

Completed

Labor

Job #	Description	Total
04	MULTIPLE LABOR CODES	9.50

Parts

Part #	Description	Qty	Price	Total
11-0583	BLADEX METAL HANDLE	1.00	4.86	4.86

W/O: 72754
Promised Date: 13 FEB 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Subtotal for Job #04: 14.36

Job #05 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Pantry behind refrigerator not staying closed

CORRECTION: Latch damaged. Replace and test

Requesting .3 hr

Completed

Labor

Job #	Description	Total
05	MULTIPLE LABOR CODES	57.00

Parts

Part #	Description	Qty	Price	Total
9999	LATCH	1.00	4.99	4.99

Subtotal for Job #05: 61.99

Job #06 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Light strip above kitchen sink detached

CORRECTION: Resecure with sealant

.5hr

Completed

Labor

Job #	Description	Total
06	MULTIPLE LABOR CODES	38.00

Subtotal for Job #06: 38.00

Job #07 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Unknown. Must disconnect and pull stove to find issue.

CORRECTION: Requesting 1.0 hr to pull stove. L.p drop test must be performed.

Found loose wire on hot at floor plug. Repaired and tested. Completed

Labor

Job #	Description	Total
07	MULTIPLE LABOR CODES	133.00

Subtotal for Job #07: 133.00

Job #08 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Light strip under fireplace detached

CORRECTION: Resecure and reseal

.3 hr

Completed

Labor

Job #	Description	Total
08	MULTIPLE LABOR CODES	19.00

W/O: 72754
Promised Date: 13 FEB 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,



Subtotal for Job #08: 19.00

Job #09 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Auto level out of calibration

CORRECTION: Reconfigured auto level zero point. Tested. Completed

.5hr
Completed

Labor

Job #	Description	Total
09	MULTIPLE LABOR CODES	47.50

Subtotal for Job #09: 47.50

Job #10 - Warranty

COMPLAINT: WARRANTY ITEM

CAUSE: Mid bunk room door has rub damage at latching area

CORRECTION: Sand, stain and resecure frame catch to allow for door clearance

.5 hr
Completed

Labor

Job #	Description	Total
10	MULTIPLE LABOR CODES	95.00

Subtotal for Job #10: 95.00

Parts Total: 9.85
 Labour Total: 551.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 560.85

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 11 Feb 2026

W/O: 72754
Promised Date: 13 FEB 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

