

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	<b>CLAIM STATUS</b> Authorized <b>CLAIM</b> 2570155 <b>CLAIM ORIGIN</b> WEB <b>ORIGINAL CLAIM ID</b> <b>VIN</b> 5ZT2AVMB2TB941424 <b>CHASSIS VIN</b> <b>MILEAGE</b> 0 <b>SITE/WAREHOUSE</b> 050 / 050 <b>ITEM #</b> AVT23BHS <b>DEALER RO #</b> 72891 <b>CLAIM START DATE</b> 02/04/2026 <b>CLAIM END DATE</b> 01/01/1900
--	--

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**      **Operation Code**      **Operational Description**  
 30-100-24-00-001043      Drawer Front - Interior/Cabinetry/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:07:20 :: Complaint: Screw pulled out of drawer latch below microwave. Cause: During SFD found that the drawer below the microwave latch catch the screws pulled out. Correction: Replace screws

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$38.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$38.00

**Notes**

### Labor

**Line# 2**      **Operation Code**      **Operational Description**  
 30-100-12-00-001049      Cabinet End Panel - Interior/Cabinetry/Resecure or Tighten/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:10:42 :: Complaint: Panel came unstapled and loose on the back side of the kitchen sink Cause: Found during SFD, the access panel for the plumbing to the kitchen sink, the staples pulled out Correction: Restapled panel and reinstalled access panel.

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b>	\$19.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$19.00

**Notes**

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 30-102-24-00-001094      Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/  
 Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:14:50 :: Complaint: Dings in the wall next to the refrigerator Cause: Found dings in wall during SFD Correction: Repair wall dings with putty stick

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$38.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$38.00

**Notes**

### Labor

**Line# 4**      **Operation Code**      **Operational Description**  
 40-197-01-11-001321      Exterior Recept Cover - Including Gasket - Electrical/110 Volt Exterior/Replace/  
 Electrical  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:16:15 :: Complaint: Weatherproof receptacle cover is missing Cause: Found during SFD that the outside receptacle cover was missing Correction: Replace

cover and reseal with clear silicone

**Model#** **Dlr Sub Hrs** 0.10

**Sub Labor Amt** \$19.00

**Serial#** **Appr Hrs** 0.10

**Appr Labor Amt** \$19.00

**Notes**

---

<b>Submitted</b>	Labor Amt	\$114.00
	Parts & Freight	\$0.00
	Total	\$114.00

---

<b>Approved</b>	Labor Amt	\$114.00
	Parts & Freight	\$0.00
	Total	\$114.00

---

**DEALER** **DATE**  
**SIGNATURE**

I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER** **DATE**  
**SIGNATURE**

All repairs described have been inspected and are satisfactory.