

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2570155
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVMB2TB941424
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT23BHS
SPENCER PATTON		DEALER RO #	72891
15 EDGE OF WOODS RD		CLAIM START DATE	02/04/2026
Tijeras, NM 87059		CLAIM END DATE	02/05/2026
USA			
Retail Date of Purchase	02/05/2026	WARRANTY EXPIRATION DATE	02/05/2027

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-100-24-00-001043	Drawer Front - Interior/Cabinetry/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:07:20 :: Complaint: Screw pulled out of drawer latch below microwave. Cause: During SFD found that the drawer below the microwave latch catch the screws pulled out. Correction: Replace screws			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
	Notes			

Part

Line# 1	Item #	Description		
	USERPART	Screws		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$1.90
	Appr Qty	1.00	Sub Freight	\$0.00
			Appr Dlr Price	\$1.90
			Appr Freight	\$0.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-100-12-00-001049	Cabinet End Panel - Interior/Cabinetry/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:10:42 :: Complaint: Panel came unstapled and loose on the back side of the kitchen sink Cause: Found during SFD, the access panel for the plumbing to the kitchen sink, the staples pulled out Correction: Restapled panel and reinstalled access panel.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
	Notes			

Part

Line# 1	Item #	Description		
	USERPART	Staples		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.95
	Appr Qty	1.00	Sub Freight	\$0.00
			Appr Dlr Price	\$0.95
			Appr Freight	\$0.00
	Notes			

Labor

Line# 3 **Operation Code** **Operational Description**
 30-102-24-00-001094 Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/
 Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:14:50 :: Complaint: Dings in the wall next to the refrigerator Cause: Found dings in wall during SFD Correction: Repair wall dings with putty stick

Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$38.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$38.00

Notes**Part**

Line# 1 **Item #** **Description**
 USERPART Putty
Model # **Serial #** **Part tag**
Sub Qty 1.00 **Sub Dlr Price** \$1.90 **Sub Freight** \$0.00
Appr Qty 1.00 **Appr Dlr Price** \$1.90 **Appr Freight** \$0.00

Notes**Labor**

Line# 4 **Operation Code** **Operational Description**
 40-197-01-11-001321 Exterior Recept Cover - Including Gasket - Electrical/110 Volt Exterior/Replace/
 Electrical

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-02-04 09:16:15 :: Complaint: Weatherproof receptacle cover is missing Cause: Found during SFD that the outside receptacle cover was missing Correction: Replace cover and reseal with clear silicone

Model# **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$19.00
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$19.00

Notes**Part**

Line# 1 **Item #** **Description**
 USERPART Receptacle cover
Model # **Serial #** **Part tag**
Sub Qty 1.00 **Sub Dlr Price** \$6.33 **Sub Freight** \$0.00
Appr Qty 1.00 **Appr Dlr Price** \$6.33 **Appr Freight** \$0.00

Notes

Submitted	Labor Amt	\$114.00	Approved	Labor Amt	\$114.00
	Parts & Freight	\$11.08		Parts & Freight	\$11.08
	Total	\$125.08		Total	\$125.08

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.