



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72906
Promised Date:
07 FEB 26



WO #: 72906

Customer Name: 61095 - PATTON,
SPENCER RILEY

Completed Date: 19 FEB 26
Invoice#: 308657
Author: BRIAN
Stock Desc: 9625 2026 AVENGER
23BHS
Serial#: 5ZT2AVMB2TB941424
Chassis#: 5ZT2AVMB2TB941424
Miles/Hrs:
Tag#: 7046
Purchased Date: 05 FEB 26
Warranty Date: 05 FEB 26

Date In: 07 FEB 26
Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES TOILET LEAK FROM BEHIND - MAY BE AT TOILET CONNECTIONS, RUNS DOWN THE BLUE HOSE AND PUDDLES BETWEEN THE SHOWER AND SINK CABINET

CAUSE: Loose fitting

CORRECTION: Found the water connection for the water line to the toilet was not tight.

Tightened the fitting

Tested with antifreeze since the unit appeared to winterized

No leaks found

Used 3 gallons of antifreeze to test the unit

Work completed .57 hours

Labor

Job #	Description	Total
1	TOILET LEAK	38.00
Subtotal for Job #1:		38.00

Job #1A - Internal

Used 3 gallons of antifreeze to test the unit

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1A: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES SHOWER PAN NEEDS TO BE SEALED

CAUSE: Missing sealant

CORRECTION: Cleaned and used white silicone on the whole edge between the shower floor and wall

Work completed .20 hours

Customer #: 61095
PATTON, SPENCER RILEY





Labor		
Job #	Description	Total
2	SHOWER PAN SEAL	38.00
Subtotal for Job #2:		38.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES CABINET BELOW BATHROOM SINK HAS HINGES ON BOTH SIDES AND WILL NOT CLOSE

CAUSE: Screws removed

CORRECTION: This unit comes from the factory with hinges on both side to prevent storage under the sink and damaging any of the plumbing
 Screws were put back in the hinges as designed
 Work completed .10 hours

Labor		
Job #	Description	Total
3	CABINET HARDWARE	19.00
Subtotal for Job #3:		19.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES EMERGENCY WINDOW AT BOTTOM BUNK HAS A GAP

CAUSE: Window itself off centered

CORRECTION: Found on the rear of the emergency lower bunk window could see light on the back side
 Removed the set screws at the top
 Centered the window reinstalled set screws window seals cant see light anymore
 Work completed .10 hours

Labor		
Job #	Description	Total
4	EMERGENCY WINDOW GAP	38.00
Subtotal for Job #4:		38.00

Job #5 - Warranty

COMPLAINT: CUSTOMER STATES WHEN ENTRY DOOR HANDLE IS CLOSED A SCREW IS STICKING OUT AND DOES NOT SIT FLUSH

CAUSE: Bottom base plate for the entry door handle installed at an angle

CORRECTION: Removed screw cover
 Removed both screws straightened the base plate
 Reinstalled the screws
 Tested the handle for movement and is working correctly
 Work complete .05 hours

Labor		
Job #	Description	Total
5	ENTRY DOOR ASSIST HANDLE	38.00
Subtotal for Job #5:		38.00

Job #6 - Warranty

COMPLAINT: CUSTOMER STATES THE OUTLET COVER ON DOOR SIDE NEEDS TO BE SILICONED BETTER

CAUSE: Silicone cracked on the top and excessive smear of silicone

CORRECTION: Scrapped off all old silicone used adhesive remover get remove the finer layer.



Resealed the black outlet cover on the black side with black silicone
Work completed .35 hours

Labor		
Job #	Description	Total
6	OUTLET COVER	38.00
Subtotal for Job #6:		38.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES THE BUMPER CAP ON DOOR SIDE IS MISSING

CAUSE: Cap is missing

CORRECTION: Replaced cap with new one work completed .05 hours

Labor				
Job #	Description	Total		
7	BUMPER END CAP	9.50		
Parts				
Part #	Description	Qty	Price	Total
70406	4" BUMPER PLUG	1.00	2.29	2.29
Subtotal for Job #7:				11.79

Job #8 - Warranty

COMPLAINT: CUSTOMER STATES SILICONE NEEDS TO BE CLEANED & RE-APPLIED AT THE REAR AND FRONT CORNER MOLDINGS - DOOR SIDE

CAUSE: Silicone cracked front and rear passenger door side corners

CORRECTION: Scrapped and resealed the front corner
Reseal rear corner with decal replacement job line
Work completed for front .20 hours

Labor		
Job #	Description	Total
8	CORNER MOLDING RESEAL	38.00
Subtotal for Job #8:		38.00

Job #9 - Warranty

COMPLAINT: CUSTOMER STATES SILICONE NEEDS TO BE CLEANED & RE-APPLIED AT THE REAR AND FRONT CORNER MOLDINGS - OFF-DOOR SIDE

CAUSE: Cracked silicone

CORRECTION: Scrapped and cleaned cracked silicone on the front off door side front lower corner
Resealed with clear silicone
No cracks found on the rear corner off door side .30 hours

Labor		
Job #	Description	Total
9	CORNER MOLDING RESEAL	57.00
Subtotal for Job #9:		57.00

Job #10 - Warranty

COMPLAINT: CUSTOMER STATES REAR ELECTRIC JACKS WILL NOT RETRACT - WHILE CUST. WAS HERE THE JACKS WOULD NOT EXTEND WHEN PUSHING BUTTON AT REAR OF TRAILER

CAUSE: No power

CORRECTION: Pulled the switch out of the frame tested for power at the switch no power found. Traced the wires to the fuse block on the frame tested power had 12v coming in power out. Removed fuse block

W/O: 72906
Promised Date: 27 FEB 26



Customer #: 61095
PATTON, SPENCER RILEY



Replaced with new fuse block tested jack up and down they now work correctly
Work completed .40 hours

Labor

Job #	Description	Total
10	ELECTRIC JACK - MOTOR	76.00

Parts

Part #	Description	Qty	Price	Total
10138	30 AMP CIR BREAKER	1.00	4.27	4.27

Subtotal for Job #10: 80.27

Job #11 - Warranty

COMPLAINT: CUSTOMER STATES UNDER SLIDE ON OFF-DOOR SIDE ELECTRICAL WIRE
SUPPORT IS HANGING

CAUSE: Electric wiring slide out support

CORRECTION: Examined the slide room electric wiring support system. It is completely intact properly
secured and holding the wiring as it should be in order for the slide to move in and out without pinching the
wires. Work completed .05 hours

Labor

Job #	Description	Total
11	ELECTRICAL SUPPORT	9.50

Subtotal for Job #11: 9.50

Job #12 - External

COMPLAINT: TOOK PICTURES OF THE DECAL FOR WO#72903 - TOWARDS THE REAR OF UNIT ON
DOOR SIDE

CAUSE: `

Parts

Part #	Description	Qty	Price	Total
38-0063	RIBBED D SEAL 3/4X1/2	7.00	N/C	N/C

Subtotal for Job #12: 0.00

Job #NOTE - External

CUSTOMER STATES TANKS ARE DRAINED BUT UNIT IS NOT WINERIZED

CUSTOMER HAS OPEN WO#72903

Subtotal for Job #NOTE: 0.00

Parts Total:	6.56
Labour Total:	399.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	405.56

W/O: 72906
Promised Date: 27 FEB 26



Customer #: 61095
PATTON, SPENCER RILEY



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 19 Feb 2026

W/O: 72906
Promised Date: 27 FEB 26



Customer #: 61095
PATTON, SPENCER RILEY



Customer Work
Order

