

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Authorized  
 CLAIM 2582616  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2AVEC3TG815373  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 452 / 452  
 ITEM # AVT16BHX-452  
 DEALER RO # 72926  
 CLAIM START DATE 02/17/2026  
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1	Operation Code 30-102-12-00-002691	Operational Description Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code
---------	---------------------------------------	---

#### Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-02-17 11:44:22 :: Complaint: Paneling at bed is separating at the bottom Cause: Panel came loose at the corner of the main bed Correction: Nail panel back in place

Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$47.50
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

#### Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

<b>Submitted</b>	Labor Amt	\$47.50	<b>Approved</b>	Labor Amt	\$38.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$47.50		Total	\$38.00

DEALER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_  
 SIGNATURE

All repairs described have been inspected and are satisfactory.