

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2582616
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2AVEC3TG815373
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 452 / 452
 ITEM # AVT16BHX-452
 DEALER RO # 72926
 CLAIM START DATE 02/17/2026
 CLAIM END DATE 02/19/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

| | | |
|---------|---|---|
| Line# 1 | Operation Code 30-102-12-00-002691 | Operational Description Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code |
| | Complaint, Cause, Correction | |
| | Original Note : stephanie@dealer-advisors.com, 2026-02-17 11:44:22 :: Complaint: Paneling at bed is separating at the bottom Cause: Panel came loose at the corner of the main bed Correction: Nail panel back in place | |
| Model# | Dlr Sub Hrs 0.25 | Sub Labor Amt \$47.50 |
| Serial# | Appr Hrs 0.20 | Appr Labor Amt \$38.00 |

Notes

NVCB,Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

| | | | | | |
|------------------|-----------------|---------|-----------------|-----------------|---------|
| Submitted | Labor Amt | \$47.50 | Approved | Labor Amt | \$38.00 |
| | Parts & Freight | \$0.00 | | Parts & Freight | \$0.00 |
| | Total | \$47.50 | | Total | \$38.00 |

DEALER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE

All repairs described have been inspected and are satisfactory.