

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2543145
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRPU1XTB035145
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 080 / 080
 ITEM # RPT194-80
 DEALER RO # 72187
 CLAIM START DATE 01/06/2026
 CLAIM END DATE 02/04/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 70-178-01-00-002145 Stove Top Cover - Appliances/Range (Suburban)/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:02:27 :: Complaint: Stove glass top is broken
 Cause: Glass top is broken, arrived this way. noted on DAF. Correction: Remove and replace glass top

Model#	CGH12D2MA1b-bl	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	10002002317062512122	Appr Hrs	0.10	Appr Labor Amt	\$19.00

Notes
 Excessive time requested. Time reduced based on photos, description and flat rate code.
 Authorized broken from the plant/production.

Part

Line# 1 **Item #** **Description**
 F100495750 STOVE,FURRIION,GLASS TOP-TRAY MODULE,FGH12D2-BL
Model # **Serial #** **Part tag**

Sub Qty	1.00	Sub Dlr Price	\$71.19	Sub Freight	\$20.44
Appr Qty	1.00	Appr Dlr Price	\$71.19	Appr Freight	\$20.44

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-92-01-00-001154 Sink Cover - Interior/Interior Miscellaneous/Replace/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:06:54 :: Complaint: Sink cover hang handle is bent and missing screw Cause: Arrived this way, noted on DAF Correction: Straightened handle holder and add a new screw

Model#		Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#		Appr Hrs	0.10	Appr Labor Amt	\$19.00

Notes
 Authorized to repalce

Part

Line# 1 **Item #** **Description**
 USERPART Screw
Model # **Serial #** **Part tag**

Sub Qty	1.00	Sub Dlr Price	\$0.95	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$0.95	Appr Freight	\$0.00

Notes

Labor

Line# 3 **Operation Code** **Operational Description**
 30-102-15-00-003365 Wall Access Panel - Interior/Panels, Ceilings, & Interior Moldings/Repair or Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:11:52 :: Complaint: Panel in front of water pump has fallen off Cause: Panel has fallen off due to faulty staples Correction: Resecure and tightened

Model# **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$19.00
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$19.00

Notes

Part

Line# 1 **Item #** **Description**
 USERPART Staples
Model # **Serial #** **Part tag**
Sub Qty 1.00 **Sub Dlr Price** \$0.95 **Sub Freight** \$0.00
Appr Qty 1.00 **Appr Dlr Price** \$0.95 **Appr Freight** \$0.00

Notes

Labor

Line# 4 **Operation Code** **Operational Description**
 20-43-24-00-001113 Exterior Sidewall AC Vent - Exterior/Exterior Miscellaneous/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-06 18:13:02 :: Complaint: AC outside cover is making a lot of noise Cause: Outside AC cover is loose Correction: Resecure and tightened

Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$57.00
Serial# **Appr Hrs** 0.30 **Appr Labor Amt** \$57.00

Notes

Submitted	Labor Amt	\$152.00	Approved	Labor Amt	\$114.00
	Parts & Freight	\$93.53		Parts & Freight	\$93.53
	Total	\$245.53		Total	\$207.53

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.