



1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$165.00

RO# : 40424 Tag# : T1J70199

Check-in: Fri Apr 17, 2026 | 1:35 PM  
Ready for Pickup: Mon Apr 20, 2026 | 11:23 AM  
Promise Time: Wed Apr 22, 2026 | 6:00 PM

**Customer**  
Paul Hassemer  
1243285  
+1 - (715) 299 - 6406  
phassemer@rentokil-terminix.com  
7832 Blue Valley Dr S  
Eau Claire, WI 54703

**Pickup-Customer**  
Same as Customer  
  
**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 Jayco JAY  
FEATHER  
1UJBB0BK8T1J70199  
2 Mi In / 2 Mi Out  
Sold Date: 10/30/2025  
Stock #: 26-22

**Service Advisor**  
KEVIN GOODIEL  
goodielk

A.	MISCELLANEOUS	CUSTOMER STATES THE LATCH FOR THE MURPHY BED DONT WORK. BED DONT STAY UP	Warranty Pay	\$49.50
----	---------------	--	--------------	---------

Job added by KEVIN GOODIEL on Fri Apr 17, 2026 | 1:35 PM

1. Latch on front Murphy bed would not latch.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50

Labor Cost: \$9.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.15	0.3	0.3	\$49.50	\$9.30

1. Spring pin was to far over, when in locked position, pin was bottomed out, and barley in lock. Removed pin latch, moved over, covering old holes, and re-installed. Tested, locks in place.

Total Labor Sale  
\$49.50

Total Labor Cost  
\$9.30

Total Parts Sale  
\$0.00

Total Parts Cost  
\$0.00

B.	MISCELLANEOUS	CUSTOMER STATES THE TABLE TRAY HAS A CUP HOLDER THATS BROKEN OFF THE TRAY	Warranty Pay	\$66.00
----	---------------	---	--------------	---------

Job added by KEVIN GOODIEL on Fri Apr 17, 2026 | 1:35 PM

1. Cup holders in trays fell out.





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$165.00

RO# : 40424 Tag# : T1J70199

Check-in: Fri Apr 17, 2026 | 1:35 PM  
Ready for Pickup: Mon Apr 20, 2026 | 11:23 AM  
Promise Time: Wed Apr 22, 2026 | 6:00 PM

<b>Customer</b> Paul Hassemer 1243285 +1 - (715) 299 - 6406	<b>Billing-Customer</b> Same as Customer	<b>Vehicle</b> 2026 Jayco JAY FEATHER 1UJBB0BK8T1J70199	<b>Service Advisor</b> KEVIN GOODIEL goodielk
--	---	--	---

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$66.00  
Labor Cost: \$12.40

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.37	0.4	0.4	\$66.00	\$12.40

1. Re-installed cup holders in tv trays. Did not have all screws, installed different, thicker screws with course threads, seemed to bite a little better.

<b>Total Labor Sale</b> \$66.00	<b>Total Labor Cost</b> \$12.40	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	------------------------------------	-----------------------------------	-----------------------------------

<b>C. MISCELLANEOUS</b>	<b>CUSTOMER STATES TPMS SENSORS ARE NOT WORKING</b>	<b>Warranty Pay</b>	<b>\$49.50</b>
-------------------------	---	---------------------	----------------

Job added by KEVIN GOODIEL on Fri Apr 17, 2026 | 1:35 PM

1. TPMS sensors not working.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: \$49.50  
Labor Cost: \$9.30

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
turnerl	-	0.25	0	0.3	\$0.00	\$9.30

1. Would not connect to my phone, used Cody phone. Checked TPMS sensors, paired, and aired accordingly to 65psi.

<b>Total Labor Sale</b> \$49.50	<b>Total Labor Cost</b> \$9.30	<b>Total Parts Sale</b> \$0.00	<b>Total Parts Cost</b> \$0.00
------------------------------------	-----------------------------------	-----------------------------------	-----------------------------------

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	\$0.00	\$0.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$165.00

RO# : 40424 Tag# : T1J70199

Check-in: Fri Apr 17, 2026 | 1:35 PM  
Ready for Pickup: Mon Apr 20, 2026 | 11:23 AM  
Promise Time: Wed Apr 22, 2026 | 6:00 PM

**Customer**  
Paul Hassemer  
1243285  
+1 - (715) 299 - 6406

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 Jayco JAY  
FEATHER  
1UJBB0BK8T1J70199

**Service Advisor**  
KEVIN GOODIEL  
goodielk

Category	Sale	Cost
Labor	\$165.00	\$31.00
Parts	\$0.00	\$0.00
Sublet	\$0.00	\$0.00
Sublet Labor	\$0.00	\$0.00
Sublet Parts	\$0.00	\$0.00
Fees	\$0.00	\$0.00
Discounts	\$0.00	-
Tax	\$0.00	-
Deductible	\$0.00	-
Insurance/Warranty	\$0.00	-
<b>Invoice Total</b>	<b>\$165.00</b>	<b>\$31.00</b>

**Clock In Info**

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
B	MISC	Fri Apr 17, 2026	1:48 PM	2:11 PM	0.37 hrs	W	turnerl	0.4 hrs
Tag: Regular Hour			Reason: -					
A	MISC	Fri Apr 17, 2026	2:11 PM	2:20 PM	0.15 hrs	W	turnerl	0.3 hrs
Tag: Regular Hour			Reason: -					
C	MISC	Fri Apr 17, 2026	2:32 PM	2:46 PM	0.25 hrs	W	turnerl	0.3 hrs
Tag: Regular Hour			Reason: -					

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
11400	40424	LINK RV	\$165.00
57200	40424	LINK RV	-\$165.00
67200	40424	LINK RV	\$31.00





1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice  
\$165.00

RO# : 40424 Tag# : T1J70199

Check-in: Fri Apr 17, 2026 | 1:35 PM  
Ready for Pickup: Mon Apr 20, 2026 | 11:23 AM  
Promise Time: Wed Apr 22, 2026 | 6:00 PM

**Customer**  
Paul Hassemer  
1243285  
+1 - (715) 299 - 6406

**Billing-Customer**  
Same as Customer

**Vehicle**  
2026 Jayco JAY  
FEATHER  
1UJBB0BK8T1J70199

**Service Advisor**  
KEVIN GOODIEL  
goodielk

**Accounting Info - Warranty**

GL Account #	Control #	Franchise	Amount
14400	turnerl	LINK RV	-\$31.00

