

Claim statement

Claim J01496095
Dealer account #: 296921
 MYERS RV CENTER, INC

Unit 58TBM0BR4R3TM3085
Chassis: 0001264456
Description; 290RLS OPEN RANGE LIGHT TT
Registration date: 03/22/2025
Mileage:

Reference:

Customer: Montoya, Tina
Repair line J01496095-001
Claim type Standard
Claim group SPLIT

Create date: 01/16/2026 **Start date** 01/15/2026 **Rep line desc:** Gray tank
Status: Confirmed **End date** 01/15/2026 **Pre auth#:** PA001314138
Status date 01/21/2026

zz964034 January 16, 2026 5:22 PM Split Pre-approval from original claim # J01492800 Repair line # J01492800-004 hofferk January 13, 2026 2:12 PM approved 1.85 to replace probe

Complaint: Gray tank reads 2/3 when empty

Cause: CompFail Component failure, sensor when connected reads continuous 1/3. When the resistor package is removed the condition goes away. Verified by removing underbelly 10 feet across.

Correction: Had to remove propane lines and clamps to lower underbelly enough to test resistor pack. I need to install probe and reconnect and test. Probe installed and system functions as designed.

Transaction type	Main Op.	Operation no	Item number	Disp. code	Adj. Reason Code	Description	Req. qty	Unit	Unit price	Req. amount	Approved quantity	Approved amount
Labor	Yes	0155013				PROBE-REPLACE	3.40		\$179.00	\$608.60	0.75	\$134.25
Labor	No	0301026				UNDERBELLY-REPAIR	1.00		\$179.00	\$179.00	1.00	\$179.00
Labor	No	0602999				LP LINE/FITTING-MISC. GENERAL REPAIRS	0.10		\$179.00	\$17.90	0.10	\$17.90
Item	No		9001525			Probe	1.00	EA	\$0.86	\$0.86	1.00	\$0.86
Charges	No					Parts markup	1.00		\$0.26	\$0.26	1.00	\$0.26

	Labor	Parts	Charges	Total
Total requested amount	\$805.50	\$0.86	\$0.26	\$806.62
Total adjusted	(\$474.35)	\$0.00	\$0.00	(\$474.35)
Total approved amount	\$331.15	\$0.86	\$0.26	\$332.27

Invoice status Invoiced
 Invoiced date 1/21/2026
 Payment reference 455267

Claim total J01496095

	Labor	Parts	Charges	Total
Total requested amount	\$805.50	\$0.86	\$0.26	\$806.62
Total adjusted	(\$474.35)	\$0.00	\$0.00	(\$474.35)
Total approved amount	\$331.15	\$0.86	\$0.26	\$332.27