



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72072
Promised Date:
40 DEC 25



WO #: 72072

Customer Name: 59318 - MONTES DE
OCA, LYDIA B

Completed Date: 23 DEC 25

Invoice#:

Author: BRIAN

Stock Desc: 9434 2025 OPEN RANGE
22MLS

Serial#: 58TBM0BM5S7543055

Date In: 22 JUL 25

Chassis#: 58TBM0BM5S7543055

Time In:

Miles/Hrs:

Tag#: 6955

Purchased Date: 21 APR 25

Warranty Date: 21 APR 25

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THE SLIDE OUT WOOD UNDERNEATH IS NOT SQUARED OFF AND IT CAUGHT THE FLOORING AND TORE IT. (COMMING IN TO START THE PROCESS AND ORDER PARTS OR WHATS NEEDED, THEN WILL COME BACK FOR THE SERVICE IN SEPTEMBER)

CAUSE: Linoleum ripped at the front corner of the slide room
Found the ply wood stopped was cut at an angle and dragging on floor

CORRECTION: The stud for the slide was cut square removing the point that was hanging on the floor the slide now operates smoothly without risk of further damage.

To repair the linoleum the slide will have to be completely removed from the unit. All facia trim work on the inside of the slide will have to be removed. The couch will have to be removed the linoleum will have to be cut to fit.

The slide room will then have to be reinstalled all trim work replaced . The couch reinstalled. It is also possible that the refrigerator which is in the slide room will have to be removed and reinstalled.

22.00 HRS APPROVED ON CLAIM: J01401684-001

INCORRECT UNIT NUMBER GIVEN ON THE ABOVE CLAIM.

Labor

Job #	Description	Total
1	SLIDE OUT ROOM DIAGNOSTIC TIME	3,931.00

Parts

Part #	Description	Qty	Price	Total
18462	FOOD GRADE SILICONE CRC	1.00	20.79	20.79
2057850	LINOLEUM, DESIGNER CAREFREE CC365 WESTPORT COASTAL FOG 96"	2.00	18.68	37.36

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 3,989.15

Job #2 - Warranty

COMPLAINT: During the linoleum repair in the front drivers side , removed the damaged linoleum and found an area where the floor was wet. This area is directly below the front drivers side window and goes into the front compartment drivers side. Examined the window and the compartment door. On the right side of the compartment door there is a gap.

Customer #: 59318
MONTES DE OCA, LYDIA B



CAUSE: Water leaking around edges of window and compartment door

CORRECTION: Cleaned the area around both the window and compartment door
Used clear silicone and sealed the edges around both the window and compartment door
.80HRS

Labor		
Job #	Description	Total
2	REPAIR LEAK	143.20

Parts	Description	Qty	Price	Total
Part #				
40170	SILICONE TUBE-CLEAR	1.00	11.91	11.91
Subtotal for Job #2:				155.11

Job #3 - Warranty

COMPLAINT: Inspecting where water could be leaking into the unit , found the gutter/drip rail on the drivers side front have separated and run off from the roof is running down the side of the unit between the roof line and gutter , found there is one screw missing and two that are loose. Found there is no sealant in this area. Recommend adding screws and tightening the loose screws. Then sealing the drip rail and spout to prevent the water from getting into the wall
.10 HRS

CAUSE: Water leaking into the unit
Found a screw missing in the down spout
Found the down spout was missing sealant

CORRECTION: Added the missing screw
Used clear silicone sealed the roof edge in this area
Used clear silicone and sealed the down spout all the way around
Work completed

Labor		
Job #	Description	Total
3	GUTTER	89.50
Subtotal for Job #3:		89.50

Parts Total:	70.06
Labour Total:	4,163.70
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	4,233.76

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 30 Dec 2025

W/O: 72072
Promised Date: 18 DEC 25



Customer #: 59318
MONTES DE OCA, LYDIA B

