

Claim statement

Claim	J01486585	Unit	58TBM0BL4T76L3063				
Dealer account #:	296921	Chassis:	0001488312				
	MYERS RV CENTER, INC	Description;	21QB COLT TT				
Reference:		Registration date:					
Customer:		Mileage:					
Repair line	J01486585-001	Create date:	12/23/2025	Start date	01/12/2026	Rep line desc:	Monitor Panel
Claim type	Standard	Status:	Confirmed	End date	01/12/2026	Pre auth#:	PA001305532
Claim group	WarrClaim	Status date	01/15/2026				
halla January 5, 2026 2:37 PM JAYCO P# 2042703 fletchm December 23, 2025 12:52 PM approved .20 hrs to replace monitor panel							

Complaint: Monitor panel is damaged

Cause: Dmgd Monitor panel is damaged and needs to be replaced

Correction: Remove and replace monitor panel

Transaction type	Main Op.	Operation no	Item number	Disp. code	Adj. Reason Code	Description	Req. qty	Unit	Unit price	Req. amount	Approved quantity	Approved amount
Labor	Yes	0155001				MONITOR PANEL COMPLETE-REPLACE	0.20		\$179.00	\$35.80	0.20	\$35.80
Item	No		2042703	CLMNOPART		PANEL,MON 3TK GENRC WMT BLK F/USE W/TNKLS WH MFR# M21VB-OS	1.00	EA	\$42.57	\$42.57	1.00	\$42.57
Charges	No					Parts markup	1.00		\$12.77	\$12.77	1.00	\$12.77

	Labor	Parts	Charges	Total		
Total requested amount	\$35.80	\$42.57	\$12.77	\$91.14	Invoice status	Invoiced
Total adjusted	\$0.00	\$0.00	\$0.00	\$0.00	Invoiced date	1/15/2026
Total approved amount	\$35.80	\$42.57	\$12.77	\$91.14	Payment reference	454436

Claim statement

Claim

J01486585

Dealer account #:

296921
MYERS RV CENTER, INC

Unit

58TBM0BL4T76L3063

Chassis:

0001488312

Description;

21QB COLT TT

Registration date:

Mileage:

Reference:

Customer:

Repair line

J01486585-002

Create date:

12/23/2025

Start date

01/12/2026

Rep line desc:

Water line

Claim type

Standard

Status:

Confirmed

End date

01/12/2026

Pre auth#:

PA001305533

Claim group

WarrClaim

Status date

01/15/2026

halla January 5, 2026 2:37 PM

JAYCO P# 2042703

fletchm December 23, 2025 12:52 PM

approved .20 hrs to replace monitor panel

Complaint:

Toilet will not flush, has no water pressure

Cause:

CompFail Water line to toilet has a kink behind the wall

Correction:

Disconnected the water line to toilet to access kink inside of cabinet. Removed water line and cut out kink in water line. Reinstalled cabinet and reconnected to toilet.

Transaction type	Main Op.	Operation no	Item number	Disp. code	Adj. Reason Code	Description	Req. qty	Unit	Unit price	Req. amount	Approved quantity	Approved amount
Labor	Yes	0709999A				DRAIN/LINE/FITTING/VALVE-MISC GENERAL REPAIRS-FRESH	1.00		\$179.00	\$179.00	1.00	\$179.00
			Labor	Parts	Charges	Total						
Total requested amount			\$179.00	\$0.00	\$0.00	\$179.00	Invoice status		Invoiced			
Total adjusted			\$0.00	\$0.00	\$0.00	\$0.00	Invoiced date		1/15/2026			
Total approved amount			\$179.00	\$0.00	\$0.00	\$179.00	Payment reference		454436			
Claim total J01486585			Labor	Parts	Charges	Total						
Total requested amount			\$214.80	\$42.57	\$12.77	\$270.14						
Total adjusted			\$0.00	\$0.00	\$0.00	\$0.00						
Total approved amount			\$214.80	\$42.57	\$12.77	\$270.14						