



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72259
 Promised Date:
 RECEIVED



WO #: 72259

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: BRIAN
 Stock Desc: 9604 2026 OPEN RANGE
 COLT 26DBS
 Serial#: 6X3087
 Chassis#: 58TBM0BP5T76C3087
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 25 AUG 25
 Time In:

Job #1 - Internal

CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Pdi travel trailer

CORRECTION: Pdi complete

Labor

Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize rv basic

CORRECTION: Completed

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,





Labor		
Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Job #2 - Warranty

Belt rail passenger side above the axle coming loose and has a split will need to be replaced
 White in color and 17 feet long
 Requesting 5 hours
 Will have to remove rear compartment door and frame
 Remove j wrap
 Remove one side of entry door
 Remove rear corner mold and vinyl insert
 Remove damaged belt rail
 Clean sealant off the unit
 Install new belt rail
 Install j wrap
 Resecure entry door
 Reinstall compartment door and frame
 Resume corner mold and vinyl insert
 Reseal with clear silicone

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: Putty clean through out unit , slide room trim and ceiling in slide room , front bedroom batten trim , lower bunk bed wall

CAUSE: Excessive putty and staples sticking up small cut on the wall in lower bunk bed

CORRECTION: Wiped down all excessive putty, set the staples sticking up and puttied the holes
 Allied putty to the cut on the wall and wiped down cut is covered up
 Work completed
 .50 HRS

Labor		
Job #	Description	Total
3	TOUCH UP	0.00

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Passenger side compartment door for outdoor kitchen is not square and will not close properly,
 Will need to remove all screws inside and get the frame square and resecure the frame so the door will close properly.

CAUSE: MISALIGNED

CORRECTION: WILL NEED TO REMOVE DOOR / RESET AND REINSTALL
 .50HRS



Subtotal for Job #4: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 12 Jan 2026

Customer Signature : _____

W/O: 72259
Promised Date: 15 SEP 25



Customer Work Order

Customer #: 1000
MYERS "RV" CENTER,
INC.,

