



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72320
 Promised Date:
 04 OCT 25



WO #: 72320 (Appointment Date: 05 SEP 2025 - Time: 08:15am)
 Customer Name: 60442 - MONTOYA, JOE
 Completed Date:
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9439 2025 OPEN RANGE ROAMER 304BHS
 Serial#: 58TCM0BR6S3DB3059 Date In: 05 SEP 25
 Chassis#: 58TCM0BR6S3DB3059 Time In:
 Miles/Hrs:
 Tag#: UNH
 Purchased Date: 02 AUG 25
 Warranty Date: 02 AUG 25

Job #1 - Internal

COMPLAINT: CUSTOMER STATES LP TANK ON DRIVERS SIDE WAS EMPTY AT DELIVERY - PLEASE FILL

CORRECTION: CUSTOMER ACCOMMODATION

Labor

Job #	Description	Total
1	LP TANKS FILL (ONE)	N/C

Parts

Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	N/C	N/C
1000	L.P. GAS	5.80	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES WHEN FURNACE ON NO HEAT COMES OUT OF BATHROOM FLOOR VENT OR BEDROOM WALL VENT

CAUSE: Furnace duct has become loose from furnace unit.
 Removed a section of under belly to find a hole in furnace ducting.
 Used 2ft of aluminum tape and 4ft of underbelly tape.

CORRECTION: Reconnected furnace duck and secured with aluminum tape.
 Repaired furnace ducting using aluminum tape. Reinstalled underbelly belly using new screw after cutting off nails used by factory.install Y connections to increase air flow to master bedroom.
 Called tech support waiting on return call.

Labor

Job #	Description	Total
2	FURNACE DUCT DIAGNOSE	N/C

Parts

Part #	Description	Qty	Price	Total
99-3364	NON-INSULATED DUCT 4"	2.00	N/C	N/C
18809	4" DUCTING "Y"	2.00	N/C	N/C

Customer #: 60442
 MONTOYA, JOE





Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES BEDROOM DOOR WILL NOT STAY OPEN

CAUSE: Bedroom door is out of alignment. Top is out further than bottom one.

CORRECTION: Realigned door hinges.

Labor

Job #	Description	Total
3	DOOR ALIGN/ADJUST	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES FLOOR IS BUBBLED BY COUCH AND TABLE

CAUSE: Floor near slide has bubble in it.

CORRECTION: Make a cut in lino in front of slide to get lino Adhesive underneath and roll out bubble and let dry. Repair cut made in front of slide also with Adhesive.

Labor

Job #	Description	Total
4	FLOOR VINYL REPAIR	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

CUSTOMER STATES STOVETOP GLASS COVER WILL NOT OPEN - WE HAVE THE GLASSTOP HERE

Labor

Job #	Description	Total
5	STOVETOP - GLASS	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	N/C	N/C

Subtotal for Job #5: 0.00

Job #6 - Internal

COMPLAINT: CUSTOMER STATES AC VENT LOUVERS - ARE RATTLING

CAUSE: Ran AC while doing repairs on unit louvers never made noise.

CORRECTION: Could not duplicate problem.

CUSTOMER ACCOMMODATION - NEW

Labor

Job #	Description	Total
6	AVC LOUVERS IN CEILING ASSEMBLY R&R (EACH)	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATE THE RETURN AIR VENT FOR THE FURNACE RATTLES ALOT AND HUMS





CAUSE: Furnace screws were loose causing rattle and hum.

CORRECTION: Re-tighten screws to furnace vent.

Labor		
Job #	Description	Total
7	FURNACE RETURN AIR VENT	N/C
Subtotal for Job #7:		0.00

Job #8 - Warranty

COMPLAINT: CUSTOMER STATES WHEN CLOSING ENTRY DOOR SHADE IT BUNCHES. **I DID NOT GET PICTURES**

CAUSE: Spring for tension string is broken.

CORRECTION: Remove and replace with new blind
 Waiting on approval.

Labor		
Job #	Description	Total
8	ENTRY DOOR WINDOW SHADE	N/C
Subtotal for Job #8:		0.00

**Job #9 - Internal
 REPAIR TIRE**

Sublet		
Description	Total	
REPAIR TIRE	N/C	
Subtotal for Job #9:		0.00

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

NOTICE:
 DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 15 Dec 2025

Customer Signature : _____

