

Claim statement

Claim J01500863
Dealer account #: 296921
 MYERS RV CENTER, INC

Unit 58TCM0BR6S3DB3059
Chassis: 0001328630
Description; 304BHS OPEN RANGE ROAMER
 LIGHT DUTY FW
Registration date: 08/02/2025
Mileage:

Reference:

Customer: Montoya, Joe
Repair line J01500863-001
Claim type Standard
Claim group WarrClaim
 hofferk January 28, 2026 12:58 PM approved 4.0 additional time

Create date: 01/28/2026 **Start date** 01/21/2026 **Rep line desc:** Furnace
Status: Confirmed **End date** 01/21/2026 **Pre auth#:** PA001325295
Status date 01/30/2026

Complaint: This is related to claim J01439115-001 for the furnace. At the time of PA, we only requested the time to repair the duct. However, in order to repair the duct, the underbelly had to be dropped. This claim is for the time it took to drop the underbelly and reinstall.

Cause: Loose When furnace is on there is no heat out of bathroom floor vent. Furnace duct came loose from furnace unit. Removed underbelly to find a hole in the furnace ducting.

Correction: Used 2ft of aluminum tape and 4ft of underbelly tape. Reconnect furnace duct and secure with aluminum tape. repair furnace ducting using aluminum tape. Reinstalled underbelly using new screw after cutting off nails used by factory. Install Y connections to increase air flow to master bedroom.

Transaction type	Main Op.	Operation no	Item number	Disp. code	Adj. Reason Code	Description	Req. qty	Unit	Unit price	Req. amount	Approved quantity	Approved amount
Labor	Yes	0301025				UNDERBELLY-REPLACE	4.00		\$179.00	\$716.00	4.00	\$716.00

zz964034 January 27, 2026 6:59 PM
 No replacement, time to drop and reinstall underbelly for furnace ducting repair on claim J01439115-001

Item	No		9001530			18809 4" Ducting "Y"	2.00	EA	\$19.92	\$39.84	2.00	\$39.84
------	----	--	---------	--	--	----------------------	------	----	---------	---------	------	---------

zz964034 January 27, 2026 6:59 PM
 No replacement, time to drop and reinstall underbelly for furnace ducting repair on claim J01439115-001

Charges	No				Escorted Freight	Shipping & Handling	1.00		\$11.00	\$11.00	0.00	\$0.00
---------	----	--	--	--	------------------	---------------------	------	--	---------	---------	------	--------

zz964034 January 27, 2026 6:59 PM
 No replacement, time to drop and reinstall underbelly for furnace ducting repair on claim J01439115-001

Item	No		9001525			99-3364 Non insulated duct 4"	2.00	EA	\$0.45	\$0.90	2.00	\$0.90
------	----	--	---------	--	--	-------------------------------	------	----	--------	--------	------	--------

zz964034 January 27, 2026 6:59 PM
 No replacement, time to drop and reinstall underbelly for furnace ducting repair on claim J01439115-001

Claim statement

Claim J01500863
Dealer account #: 296921
 MYERS RV CENTER, INC

Unit 58TCM0BR6S3DB3059
Chassis: 0001328630
Description; 304BHS OPEN RANGE ROAMER
 LIGHT DUTY FW
Registration date: 08/02/2025
Mileage:

Reference:
Customer: Montoya, Joe

Charges	No	Parts markup	1.00	\$12.22	\$12.22	1.00	\$12.22
---------	----	--------------	------	---------	---------	------	---------

zz964034 January 27, 2026 6:59 PM

No replacement, time to drop and reinstall underbelly for furnace ducting repair on claim J01439115-001

	Labor	Parts	Charges	Total
Total requested amount	\$716.00	\$40.74	\$23.22	\$779.96
Total adjusted	\$0.00	\$0.00	(\$11.00)	(\$11.00)
Total approved amount	\$716.00	\$40.74	\$12.22	\$768.96

Invoice status Invoiced
 Invoiced date 1/30/2026
 Payment reference 456119

Claim total J01500863	Labor	Parts	Charges	Total
Total requested amount	\$716.00	\$40.74	\$23.22	\$779.96
Total adjusted	\$0.00	\$0.00	(\$11.00)	(\$11.00)
Total approved amount	\$716.00	\$40.74	\$12.22	\$768.96