

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794 MYERS RV CENTER INC 12024 CENTRAL AVE S.E. ALBUQUERQUE, NM 87123 USA	CLAIM STATUS Authorized CLAIM 2543967 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2AVRBXTB940854 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 050 / 050 ITEM # AVT26DBS DEALER RO # 72120 CLAIM START DATE 01/07/2026 CLAIM END DATE 01/01/1900
Labor rate: \$190.00 OWNER INFORMATION	

Retail Date of Purchase	WARRANTY EXPIRATION DATE
--------------------------------	---------------------------------

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description	
30-101-36-00-001078	Sliding, Pocket Door - Interior/Interior Doors/Touch Up/No Tread Code	
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:50:24 :: Complaint: Bedroom door upper corner has scratches Cause: Bedroom barn door has scratches on upper corner and down below Correction: Used Phil stick to color in scratches on the upper and lower section of the door.		
Model#	Dlr Sub Hrs	Sub Labor Amt \$38.00
	0.20	
Serial#	Appr Hrs	Appr Labor Amt \$38.00
	0.20	
Notes		
NVCB .20 to use putty ti fill in and cover the scratches on the sliding pocket door. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.		

Labor

Line# 2

Operation Code	Operational Description	
30-102-01-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Replace/No Tread Code	
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:54:06 :: Complaint: Trim above door wallpaper is bubbling Cause: Trim above doorway wallpaper is peeling Correction: Trim needs to be removed and replaced with new piece		
Model#	Dlr Sub Hrs	Sub Labor Amt \$95.00
	0.50	
Serial#	Appr Hrs	Appr Labor Amt \$38.00
	0.20	
Notes		
The time requested is excessive for this repair, time adjusted. VCB .20 to R&R the trim due to it delaminating. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.		

Labor

Line# 3

Operation Code	Operational Description	
30-474-12-00-003344	Bracket - Interior/Appliance Securement/Resecure or Tighten/No Tread Code	
Complaint, Cause, Correction		
Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:55:54 :: Complaint: Outside fridge is loose Cause: Outside fridge is loose due to hold down brackets missing screws Correction: Resecure outside fridge by installing new screws into the hold down brackets		
Model#	Dlr Sub Hrs	Sub Labor Amt \$57.00
	0.30	
Serial#	Appr Hrs	Appr Labor Amt \$38.00
	0.20	
Notes		
The time requested is excessive for this repair, time adjusted. NVCB .20 to secure the loose mini fridge. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.		

Labor

Line# 4 **Operation Code** **Operational Description**
 20-66-02-00-000664 Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-07 13:57:32 :: Complaint: Entry door does not close
 Cause: Front door does not close due to Lexus being out of alignment Correction: Realigned both door and frame latches to make contact with doors closed

Model# **Dlr Sub Hrs** 0.30 **Sub Labor Amt** \$57.00

Serial# **Appr Hrs** 0.30 **Appr Labor Amt** \$57.00

Notes

Labor

Line# 5 **Operation Code** **Operational Description**
 30-99-01-00-001012 Mini-Blind - Interior/Soft Goods/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-07 14:00:56 :: Complaint: Kitchen blind is damaged
 Cause: Kitchen blind is damaged Correction: Replace kitchen blind with new one

Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$38.00

Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$38.00

Notes

Submitted			Approved		
Labor Amt	\$285.00		Labor Amt	\$209.00	
Parts & Freight	\$0.00		Parts & Freight	\$0.00	
Total	\$285.00		Total	\$209.00	

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.