



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72339
 Promised Date:
 26 SEP 25



WO #: 72339

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 07 JAN 26

Invoice#:
 Author: BRIAN
 Stock Desc: 9608 2026 TRACER 235RK
 Serial#: 526454
 Chassis#: 5ZT2TRNB7TB526454
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 09 SEP 25
 Time In:

Job #1 - Internal

CHECK IN NEW UNIT

Labor

Job #	Description	Total
1	DIAGNOSIS	N/C
Subtotal for Job #1:		0.00

Job #2 - Warranty

COMPLAINT: Slide seal fell off.

CAUSE: Slide seal has fallen off rear of slide.

CORRECTION: Reinstalled seal with adhesive and new new staples.
 .30HRS

Labor

Job #	Description	Total
2	SLIDE SEAL	57.00
Subtotal for Job #2:		57.00

Job #3 - Warranty

COMPLAINT: Microwave is loose from face plate.

CAUSE: Screws that hold microwave to faceplate have fallen off.

CORRECTION: Removed microwave and installed new screws securing microwave in place.
 .20HRS

Labor

Job #	Description	Total
3	MICROWAVE	38.00
Subtotal for Job #3:		38.00

Job #4 - Warranty

COMPLAINT: Living room A/C mskes a lot noise.

CAUSE: A/C unit above coach is loose causing it to rattle.

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



CORRECTION: Remove inner vent to access hold down bolts and tighten down to hold A/C in place.
.30HRS

Labor		
Job #	Description	Total
4	AVC DIAGNOSIS	57.00
Subtotal for Job #4:		57.00

Job #5 - Warranty

COMPLAINT: Heater duct in bathroom has no airflow.

CAUSE: Heater vent in bathroom has no flow due to hose at rear has fallen off.

CORRECTION: Attached heater hose back onto vent and secured with aluminum tape.
.30HRS

Labor		
Job #	Description	Total
5	DUCTING	57.00
Subtotal for Job #5:		57.00

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: PDI Needed.

CORRECTION: PDI Completed.

Labor		
Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Parts				
Part #	Description	Qty	Price	Total
1000	L.P. GAS	10.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize unit.

CORRECTION: Winterized unit.

Labor		
Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts				
Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	2.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

W/O: 72339
Promised Date: 20 SEP 25



Customer #: 1000
MYERS "RV" CENTER,
INC.,



W/O: 72339
Promised Date: 20 SEP 25

Parts Total:	0.00
Labour Total:	209.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	209.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 07 Jan 2026

Customer Signature : _____



Customer Work Order

Customer #: 1000
MYERS "RV" CENTER,
INC.,

