

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Authorized
 CLAIM 2543735
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2TRNB7TB526454
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 048 / 048B
 ITEM # TRT235RK
 DEALER RO # 72339
 CLAIM START DATE 01/07/2026
 CLAIM END DATE 01/01/1900

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 10-11-01-00-000205 Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:08:39 :: Complaint: Slide seal fell off Cause: Slide seal has fallen off of the rear of slide Correction: Reinstalled seal with adhesive and new staples

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt \$57.00

Notes
 NVCB .30 to secure the slide out seal. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp Changed to the correct code. Dp.

Labor

Line# 2 **Operation Code** **Operational Description**
 70-150-02-00-001753 High Pointe Microwave Trim Ring - Appliances/Microwaves/Adjust/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:10:05 :: Complaint: Microwave is loose from face plate Cause: Screws that hold microwave to faceplate have fallen off Correction: Removed microwave and installed new screws securing microwave in place

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$38.00

Notes
 NVCB .20 to secure the microwave. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp

Labor

Line# 3 **Operation Code** **Operational Description**
 30-92-01-00-000481 Vent - Interior/Interior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:24:46 :: Complaint: Living room AC makes a lot of noise Cause: AC unit above coach is loose causing it to rattle Correction: Remove inner vent to access hold down bolts and tighten down to hold AC in place Additional Note : stephanie@dealer-advisors.com, 2026-01-07 12:28:27 :: No flat rate code for this repair

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt \$57.00

Notes
 NVCB .30 to secure the AC. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Labor

Line# 4 **Operation Code** **Operational Description**
 70-173-24-00-002113 Furnace Heat Duct 4" - Coiled - Appliances/Furnace (Dometic, Atwood)/Repair/
 No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:29:31 :: Complaint: Heater duct in bathroom has no airflow Cause: Heater vent in bathroom has no flow due to hose at rear has fallen off Correction: Attached heater hose back onto vent and secure with aluminum tape

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes

NVCB .30 to secure the duct. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Submitted	Labor Amt	\$209.00	Approved	Labor Amt	\$209.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$209.00		Total	\$209.00

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.