

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2543735
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRNB7TB526454
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT235RK
		DEALER RO #	72339
		CLAIM START DATE	01/07/2026
		CLAIM END DATE	01/08/2026
Retail Date of Purchase		WARRANTY EXPIRATION DATE	

Labor			
Line# 1	Operation Code	Operational Description	
	10-11-01-00-000205	Slide Out Seal, each - Frame & Chassis/Slide Out System-Seals/Replace/No Tread Code	
	Complaint, Cause, Correction		
	Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:08:39 :: Complaint: Slide seal fell off Cause: Slide seal has fallen off of the rear of slide Correction: Reinstalled seal with adhesive and new staples		
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt \$57.00
	Notes		
	NVCB .30 to secure the slide out seal. Repair only close code per dealer's description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp Changed to the correct code. Dp.		

Line# 1	Item #		Description			
	USERPART		Staples			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight	\$0.00
	Notes					

Line# 2	Operation Code		Operational Description	
	70-150-02-00-001753		High Pointe Microwave Trim Ring - Appliances/Microwaves/Adjust/No Tread Code	
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:10:05 :: Complaint: Microwave is loose from face plate Cause: Screws that hold microwave to faceplate have fallen off Correction: Removed microwave and installed new screws securing microwave in place			
	Model#	Dlr Sub Hrs	0.20	Sub Labor Amt
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00
Notes				
NVCB .20 to secure the microwave. Repair only close code per dealer's description of this repair.				
This authorization is pending ALL requirements of repair code have been met. Dp				

Line# 1	Item #	Description				
	USERPART	Screws				
	Model #	Serial #	Part tag			
	Sub Qty	1.00	Sub Dlr Price	\$1.90	Sub Freight	\$0.00

Appr Qty	1.00	Appr Dlr Price	\$1.90	Appr Freight	\$0.00
Notes					

Labor

Line# 3 Operation Code Operational Description
 30-92-01-00-000481 Vent - Interior/Interior Miscellaneous/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:24:46 :: Complaint: Living room AC makes a lot of noise Cause: AC unit above coach is loose causing it to rattle Correction: Remove inner vent to access hold down bolts and tighten down to hold AC in place Additional Note : stephanie@dealer-advisors.com, 2026-01-07 12:28:27 :: No flat rate code for this repair

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
---------	----------	------	----------------	---------

Notes

NVCB .30 to secure the AC. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Labor

Line# 4 Operation Code Operational Description
 70-173-24-00-002113 Furnace Heat Duct 4" - Coiled - Appliances/Furnace (Dometic, Atwood)/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : stephanie@dealer-advisors.com, 2026-01-07 12:29:31 :: Complaint: Heater duct in bathroom has no airflow Cause: Heater vent in bathroom has no flow due to hose at rear has fallen off Correction: Attached heater hose back onto vent and secure with aluminum tape

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00
---------	----------	------	----------------	---------

Notes

NVCB .30 to secure the duct. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

Part

Line# 1	Item #	Description			
	USERPART	Aluminum tape			
	Model #	Serial #	Part tag		
	Sub Qty	Sub Dlr Price	Sub Freight	\$0.00	
	Appr Qty	Appr Dlr Price	Appr Freight	\$0.00	

Notes

Submitted	Labor Amt	\$209.00	Approved	Labor Amt	\$209.00
	Parts & Freight	\$7.60		Parts & Freight	\$7.60
	Total	\$216.60		Total	\$216.60

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.