

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2460766
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2AVSB0SB938829
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	050 / 050
OWNER INFORMATION		ITEM #	AVT27DBS-1
TIMOTHY SANDERS		DEALER RO #	72380
31 HOLIDAY LOOP		CLAIM START DATE	10/07/2025
Tijeras, NM 87059		CLAIM END DATE	01/22/2026
USA			
Retail Date of Purchase	10/17/2024	WARRANTY EXPIRATION DATE	10/17/2025

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-58-01-00-000608	Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : b.parrott@myersrv.com, 2025-10-07 16:41:39 :: CUSTOMER STATES METAL AT PASSENGER SIDE BOWS OUT WHILE IN TRANSIT / NOT SECURED PROPERLY / REMOVE METAL FROM THE BOTTOM UP. RESTAPLE AND RESECURE METAL. AWNING, WINDOWS, ENTRY DOOR, COMPARTMENT DOOR MUST ALL BE REMOVED AND REINSTALLED AND SEALED.			
Model#	Dlr Sub Hrs	8.00	Sub Labor Amt \$1,520.00	
Serial#	Appr Hrs	6.00	Appr Labor Amt \$1,140.00	
	Notes			
	We will need pictures of the complete side of the unit. CB Pictures attached On this side of the unit where is the issue? CB You can see the metal bowing while in transit in front of the awning (Picture 1). The metal is loose from the front to the awning arm. Excessive amount requested. Authorized for 6 hours to R/I moldings and secure metal. NVCB CB			

Labor

Line# 2	Operation Code	Operational Description		
	20-58-01-00-000608	Metal - Aluminum Siding, each sheet - Exterior/Metal, Aluminum Siding/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : b.parrott@myersrv.com, 2025-10-07 16:51:30 :: CUSTOMER STATES METAL AT DRIVER SIDE BOWS OUT WHILE IN TRANSIT / NOT SECURED PROPERLY / THREE PIECES OF METAL DAMAGED AND WILL NEED TO BE REPLACED WITH DECALS. METAL MUST BE REMOVED FROM THE BOTTOM UP TO SECURE THE METAL PROPERLY. WINDOW AND SLIDE FLANGE WILL NEED TO BE REMOVED.			
Model#	Dlr Sub Hrs	8.00	Sub Labor Amt \$1,520.00	
Serial#	Appr Hrs	6.50	Appr Labor Amt \$1,235.00	
	Notes			
	So this is only happening from the slide out to the front of the unit? CB It appears it is only happening at the front of both sides. Excessive amount requested. Authorized for 6.5 hour to R/R three pieces of metal. NVCB CB			

Part

Line# 1	Item #	Description			
	USERPART	5302 Silicone caulk sealant - black			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$11.13	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$11.13	Appr Freight \$0.00

Notes

Line# 2	Item #		Description			
	USERPART		18793 Magnetic Compartment Door holder - black			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$4.29	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$4.29	Appr Freight	\$0.00

Notes

Line# 3	Item #		Description			
	USERPART		40170 Silicone Tube - Clear			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$10.53	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$10.53	Appr Freight	\$0.00

Notes

Line# 4	Item #		Description			
	USERPART		Dicor Self Leveling Sealant			
	Model #		Serial #		Part tag	
	Sub Qty	2.00	Sub Dlr Price	\$14.84	Sub Freight	\$0.00
	Appr Qty	2.00	Appr Dlr Price	\$14.84	Appr Freight	\$0.00

Notes

Line# 5	Item #		Description			
	F100418316		GRAPHIC, AVENGER 2024, DC 1 LH, 150785 98D			
	Model #		Serial #		Part tag	
	Sub Qty	3.00	Sub Dlr Price	\$42.52	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$14.17	Appr Freight	\$0.00

Notes

	Only ordered (1) decal on sales order S5296302					
Line# 6	Item #		Description			
	F100418319		GRAPHIC, AVENGER 2024, DC 2 LH, 150787 98D			
	Model #		Serial #		Part tag	
	Sub Qty	3.00	Sub Dlr Price	\$34.67	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$11.56	Appr Freight	\$0.00

Notes

	Only ordered (1) decal on sales order S5296302					
Line# 7	Item #		Description			
	F100636747		METAL, .030 16 X 159-1/2, 1MDM SL BRANDYWINE GREYHOUND TC, 0301615965			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$56.17	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$51.35	Appr Freight	\$0.00

Notes

	Dealer has submitted a part cost different than what was charged on the Forest River parts order, S5296302. The approved cost has been adjusted to \$44.65 + state allowed mark-up of 15%.					
Line# 8	Item #		Description			
	F100636781		METAL, .030 16" X 159-1/2, 1MDM SL POLAR WHITE/GREYHOUND TC, 0301615975			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$50.68	Sub Freight	\$0.00
	Appr Qty	1.00	Appr Dlr Price	\$50.68	Appr Freight	\$0.00

Notes

Line# 9	Item #		Description			
----------------	---------------	--	--------------------	--	--	--

F100636808

METAL, 030 16" X 320", 1MDM SL COACHMEN GRAY/GREYHOUND TC,
0301632090

Model #

Serial #

Part tag

Sub Qty 1.00

Sub Dlr Price \$103.02

Sub Freight \$430.61

Appr Qty 1.00

Appr Dlr Price \$103.02

Appr Freight \$430.61

Notes

Submitted

Labor Amt \$3,040.00
Parts & Freight \$758.46
Total \$3,798.46

Approved

Labor Amt \$2,375.00
Parts & Freight \$702.18
Total \$3,077.18

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.