



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72408
Promised Date:
46 DEC 25



WO #: 72408 (Appointment Date: 27 SEP 2025 - Time: 09:15am)

Customer Name: 60534 - DUNLAP,
LESLIE JO

Completed Date:
Invoice#: 307150
Author: ADVISOR
Stock Desc: 9573 2026 AVENGER
26DBS
Serial#: 5ZT2AVRBXTB940952
Chassis#: 5ZT2AVRBXTB940952
Miles/Hrs:
Tag#: 6831
Purchased Date: 23 AUG 25
Warranty Date: 23 AUG 25

Date In: 27 SEP 25
Time In:

Job #1 - External

TO ADDRESS FIRST TRIP ISSUES

Labor

Job #	Description	Total
1	DIAGNOSIS	0.00
Subtotal for Job #1:		0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THE RED BAR ON THE DRIVERS SIDE REAR STABILIZER JACK IS DISCONNECTED

CAUSE: Both bars on the side of the stabilizer are bent and broken the jack is bent and side mounts for the side bars are bent

CORRECTION: Recommend the full replacement
Remove damaged jack disconnect the power
Install new jack and reconnect the power
Request 1.5 hours
Removed bent arms
Only received one arm
Need 5 1/2 bolt and the other arms to complete this job
One arm partially installed to hold jack in place so the unit can be moved

Labor

Job #	Description	Total
2	STABILIZER SISSOR JACK BAR	N/C

Parts

Part #	Description	Qty	Price	Total
F100801597	STABILIZER BAR ONLY - YELLOW (16.09 X 1.19 X 1.69 X .21)	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Customer #: 60534
DUNLAP, LESLIE JO



W/O: 72408
Promised Date: 16 DEC 25



Customer #: 60534
DUNLAP, LESLIE JO



Job #3 - External

COMPLAINT: CUSTOMER STATES EQUILIZER BAR ON PASS. SIDE IS MISSING - HAD IT DURING DELIVERY BUT WHEN THEY GOT HOME IT WAS GONE

CAUSE: Eq bar missing
Tongue attachment damaged

CORRECTION: Recommend replacement of the bolt on attachment for the tongue and replace eq bar see photos

Eq arm received and placed in the front storage compartment

Labor

Job #	Description	Total
3	SWAY BAR	25.35

Parts

Part #	Description	Qty	Price	Total
14-0071	8K HITCH BAR ONLY - EAZ LIFT	1.00	149.44	149.44

Subtotal for Job #3: 174.79

Job #4 - External

COMPLAINT: CUSTOMER REQUESTS INSTALL LICENSE PLATE - IT WILL BE IN THE SINK

CAUSE: Not installed

CORRECTION: Installed plate with lock nuts
Job complete

Labor

Job #	Description	Total
4	LICENSE PLATE INSTALL	39.00

Other Services

Code	Description	Qty	Price	Total
SS-I	SHOP SUPPLIES - INTERNAL	1.00	0.00	0.00

Subtotal for Job #4: 39.00

Parts Total:	149.44
Labour Total:	64.35
Sublet Total:	0.00
Extras Total:	0.00
Tax Total:	16.30
WORK ORDER TOTAL:	230.09

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 18 Dec 2025

