



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72468
Promised Date:
10 OCT 25



WO #: 72468

Customer Name: 60749 - CECIL, LINDA
KAY

Completed Date: 19 DEC 25

Invoice#:

Author: BRIAN

Stock Desc: 9491 2025 TRACER 190RB

Serial#: 5ZT2TRHB2SB525920

Chassis#: 5ZT2TRHB2SB525920

Miles/Hrs:

Tag#:

Purchased Date: 09 OCT 25

Warranty Date: 09 OCT 25

Date In: 09 OCT 25

Time In:

Job #1 - Warranty

COMPLAINT: WATER PRESSURE WEAK / NO HOT WATER

CAUSE: Component failure

CORRECTION: Verified customers concern. Water heater would not come on due to flow rate. Removed aerator in bathroom and removed debris as shown in picture. Water pressure improved slightly, but not enough to turn water heater on and keep it on. Checked kitchen faucet for pressure to ensure That pressure was equal across all fixtures. Eliminating fixture issues. Located water pump gained access to water pump by removing access cover. Installed known good hose to a jug of water issue was resolved. Inspection of filter housing and inlet hose showed screen. Housing had manufacturing defect. Plastic was not all the way removed from inlet. Replaced screen and housing with new. Tested system, no further issues noted reassembled all disassembled items in reverse order

Labor

Job #	Description	Total
1	WATER SYSTEM TROUBLESHOOT	N/C

Parts

Part #	Description	Qty	Price	Total
24051	IN-LINE FILTER	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SHOWER HEAD LEAKING

CAUSE: Debris and orifices

CORRECTION: Verified customer concern. Excessive debris throughout orifices attempted to blow out with air gun reattached and tested. Still leaking water. Replaced with non-good part issue was resolved.

Labor

Job #	Description	Total
2	SHOWER HEAD	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

COMPLAINT: SPEAKER HAS LOW VOLUME

CAUSE: Could not duplicate concern

Customer #: 60749
CECIL, LINDA KAY



W/O: 72468
Promised Date: 10 OCT 25



Customer #: 60749
CECIL, LINDA KAY



CORRECTION: Could not verify customers concern. Compared speaker to stock unit speaker both have same volume.

Labor		
Job #	Description	Total
3	DIAGNOSIS	N/C
Subtotal for Job #3:		0.00

Job #4 - Warranty

COMPLAINT: Bed base woodgrain panel bowed

CAUSE: Incorrect installation

CORRECTION: Panel awas cut too long. Removed both vertical corner trim. Removed panel. And cut a quarter inch off. Removed all old fasteners from lumber, reattached wood, green panel and corner trim. Filled nail holes and staple holes.

Labor				
Job #	Description			Total
4	BED PANEL			N/C
Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #4:				0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 19 Dec 2025

