



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72469
 Promised Date:
 10 NOV 25



WO #: 72469

Customer Name: 60254 - GARCIA,
 JACOB MICHAEL

Completed Date: 19 DEC 25

Invoice#:
 Author: ADVISOR
 Stock Desc: 9424 2025 TRACER
 240BHSLE
 Serial#: 5ZT2TRNB7SB525514
 Chassis#: 5ZT2TRNB7SB525514
 Miles/Hrs:
 Tag#: 6903
 Purchased Date: 11 JUL 25
 Warranty Date: 11 JUL 25

Date In: 09 OCT 25

Time In:

Job #0 - External

CUSTOMER HAS OPEN WO#72136

Labor

Job #	Description	Total
0	DIAGNOSIS	N/C
Subtotal for Job #0:		0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES PASS. SIDE FENDERSKIRT NEEDS SOME SILICONE

CAUSE: Cracked silicone

CORRECTION: Found the silicone on the passenger side fender skirt on both ends cracked
 Used a tube of clear silicone resealed both ends of the fender skirt
 Work completed

Labor

Job #	Description	Total
1	SILICONE FENDERSKIRT	19.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00
Subtotal for Job #1:				19.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES UNDER KITCHEN SINK PIPE IS BROKE

CAUSE: Fitting broke between the one way trap and the 1 1/2 abs

CORRECTION: Opened the cabinet cut the broke fitting off the abs pipe and removed one way trap. Used a new swivel fitting and 1 1/2 coupler glued the couple to the fitting and to the abs pipe threaded the one way trap back on and reattached it to the sink
 Work completed

Labor

Job #	Description	Total
2	DRAIN PIPE REPLACE	95.00

Customer #: 60254
 GARCIA, JACOB MICHAEL





Part #	Description	Qty	Price	Total
02-2329	1-1/2 ABS COUPLER	2.00	2.15	4.30
56010	SWIVEL ADAPTER 1 1/2"	1.00	4.88	4.88
17766	1/2" PEX PLASTIC SWIVEL ELBOW	1.00	2.86	2.86
88-9165	1/2 PLUMB-PEX CLAMP (OETIKER)	1.00	0.88	0.88

Subtotal for Job #2: 107.92

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES UNDER MICROWAVE FURRIION RANGE HOOD LOOSE ON SIDE CLOSEST TO WALL

CAUSE: Screws stripped in range hood

CORRECTION: Found the front two screws were stripped. Moved the screws to new hole added one screw to the top and one to the back. Hood now secure. Work completed

Job #	Description	Total
3	SECURE RANG HOOD	19.00

Subtotal for Job #3: 19.00

Job #4 - Warranty

COMPLAINT: CUSTOMER STATES OVEN BURNER HAS COME OFF

CAUSE: Oven burner fell off no screws located

CORRECTION: Placed oven burner back into the correct position. Added 2 screws with nuts and secured the burner back to the base plate. Tested the oven for operation worked correctly
 Work completed

Job #	Description	Total
4	BURNER ASSEMBLY (OVEN), R & R	95.00

Subtotal for Job #4: 95.00

Job #5 - Warranty

COMPLAINT: Transferred to RV*72469-1 on 05 DEC 25

Estimate amount was 0.00

CUSTOMER STATES THIRD DRAWER FROM TOP IS HARD TO CLOSE. NEED TO PUSH TO RIGHT TO CLOSE

CAUSE: Drawer rail broken

CORRECTION: Recommend replacement of both drawer rails 15 inches in length see photo.
 Parts need to be ordered

Job #	Description	Total
5	CABINET DRAWER ADJUST	0.00

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: Transferred to RV*72469-1 on 05 DEC 25

Estimate amount was 0.00

CUSTOMER STATES LIGHT COVER IN FRIDGE IS BROKE

CAUSE: Light cover broken clip on the right broken off

CORRECTION: Found the light cover is broken the clip on the right is gone.



Recommend replacement
Hold for parts - need to order

Labor

Job #	Description	Total
6	LIGHT COVER	0.00

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES CONNECTORS IN OUTSIDE FRIDGE COMPARTMENT HAVE COME DISCONNECTED

CAUSE: 90 degree swivel elbow broken

CORRECTION: Found the swivel elbow was missing customer stated it was broken
Removed the plug the was installed.
Replaced the elbow and clamped it in place. Reattached to the outdoor sprayer and reinstalled the access panel. Work completed

Labor

Job #	Description	Total
7	CONNECTIONS	57.00

Subtotal for Job #7: 57.00

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize tv

CORRECTION: Complete

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
SS-I	SHOP SUPPLIES - INTERNAL	1.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Parts Total:	12.92
Labour Total:	285.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	297.92

W/O: 72469
Promised Date: 19 NOV 25



Customer #: 60254
GARCIA, JACOB MICHAEL



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 27 Jan 2026

Customer Signature : _____

Customer Work Order

W/O: 72466
Promised Date: 19 NOV 25



Customer #: 60254
GARCIA, JACOB MICHAEL

