

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0008794	CLAIM STATUS	Paid
MYERS RV CENTER INC		CLAIM	2473274
12024 CENTRAL AVE S.E.		CLAIM ORIGIN	WEB
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRNB7SB525514
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT240BHSLE
JACOB MICHAEL GARCIA		DEALER RO #	72469
2216 VIOLETA CIR SE		CLAIM START DATE	10/20/2025
Rio Rancho, NM 87124		CLAIM END DATE	01/28/2026
USA			
Retail Date of Purchase	07/11/2025	WARRANTY EXPIRATION DATE	07/11/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-73-24-00-000739	Fenderskirt - Exterior/Fender Skirts, Wheel Well/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ryliefayth@gmail.com, 2025-10-20 14:15:57 :: CUSTOMER STATES PASS. SIDE FENDERSKIRT NEEDS SOME SILICONE / Cracked silicone / Found the silicone on the passenger side fender skirt on both ends cracked Used a tube of clear silicone resealed both ends of the fender skirt Work completed			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
	Notes			
	The time for this repair has been adjusted. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.			

Part

Line# 1	Item #	Description		
	USERPART	Silicone		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$0.95
	Appr Qty	1.00	Sub Freight	\$0.00
			Appr Dlr Price	\$0.95
			Appr Freight	\$0.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	60-139-24-00-001556	Galley Sink - Plumbing/Kitchen (Galley) Sink/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : ryliefayth@gmail.com, 2025-10-20 14:21:31 :: CUSTOMER STATES UNDER KITCHEN SINK PIPE IS BROKE / Fitting broke between the one way trap and the 1 1/2 abs / Opened the cabinet cut the broke fitting off the abs pipe and removed one way trap. Used a new swivel fitting and 1 1/2 coupler glued the couple to the fitting and to the abs pipe threaded the one way trap back on and reattached it to the sink Work completed			
Model#	Dlr Sub Hrs	0.70	Sub Labor Amt	\$133.00
Serial#	Appr Hrs	0.50	Appr Labor Amt	\$95.00
	Notes			
	The time for this repair has been adjusted. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.			

Part

Line# 1	Item #	Description		
	USERPART	1-1/2 ABS COUPLER		
	Model #	Serial #	Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$2.47
			Sub Freight	\$0.00

Appr Qty	1.00	Appr Dlr Price	\$2.47	Appr Freight	\$0.00
----------	------	----------------	--------	--------------	--------

Notes

Line# 2	Item #	Description			
	USERPART	SWIVEL ADAPTER 1 1/2"			
	Model #	Serial #		Part tag	
	Sub Qty	Sub Dlr Price	\$5.61	Sub Freight	\$0.00
	Appr Qty	Appr Dlr Price	\$5.61	Appr Freight	\$0.00

Notes

Line# 3	Item #	Description			
	USERPART	1/2" PEX PLASTIC SWIVEL ELBOW			
	Model #	Serial #		Part tag	
	Sub Qty	Sub Dlr Price	\$3.29	Sub Freight	\$0.00
	Appr Qty	Appr Dlr Price	\$3.29	Appr Freight	\$0.00

Notes

Line# 4	Item #	Description			
	USERPART	1/2 PLUMB-PEX CLAMP (OETIKER)			
	Model #	Serial #		Part tag	
	Sub Qty	Sub Dlr Price	\$1.01	Sub Freight	\$0.00
	Appr Qty	Appr Dlr Price	\$1.01	Appr Freight	\$0.00

Notes

Labor

Line# 3	Operation Code	Operational Description			
	70-164-24-00-000501	Range Hood - Appliances/Range Hood/Repair/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : ryliefayth@gmail.com, 2025-10-22 09:04:51 :: CUSTOMER STATES UNDER MICROWAVE FURRIION RANGE HOOD LOOSE ON SIDE CLOSEST TO WALL / Screws stripped in range hood / Found the front two screws were stripped. Moved the screws to new hole added one screw to the top and one to the back. Hood now secure. Work completed				
	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
	Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00
	Notes				
	The time for this repair has been adjusted. This repair is approved as described by the dealer. This authorization is pending ALL requirements of repair code have been met.				

Part

Line# 1	Item #	Description			
	USERPART	Screws			
	Model #	Serial #		Part tag	
	Sub Qty	Sub Dlr Price	\$0.95	Sub Freight	\$0.00
	Appr Qty	Appr Dlr Price	\$0.95	Appr Freight	\$0.00

Notes

Labor

Line# 4	Operation Code	Operational Description			
	70-179-01-00-002166	Burner Assembly - Appliances/Cooktop (Dometic)/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : ryliefayth@gmail.com, 2025-10-22 09:13:39 :: CUSTOMER STATES OVER BURNER HAS COME OFF / Oven burner fell off no screws located / Placed oven burner back into the correct position. Added 2 screws with nuts and secured the burner back to the base plate. Tested the oven for operation worked correctly Work completed Additional Note : ryliefayth@gmail.com, 2025-10-22 09:24:19 :: Not replace, but resecure screws on burner assembly				
	Model# 0	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
	Serial# 0	Appr Hrs	0.50	Appr Labor Amt	\$95.00

Notes

Part

Line# 1	Item #	Description			
	USERPART	Screws and nuts			
	Model #	Serial #	Part tag	0000399875	
	Sub Qty	1.00	Sub Dlr Price	\$4.75	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$4.75	Appr Freight \$0.00

Notes

Labor

Line# 7	Operation Code	Operational Description			
	40-197-01-11-001419	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/ Electrical			
	Complaint, Cause, Correction				
	Original Note : ryliefayth@gmail.com, 2025-10-22 09:33:35 :: CUSTOMER STATES CONNECTORS IN OUTSIDE FRIDGE COMPARTMENT HAVE COME DISCONNECTED / 90 degree swivel elbow broken / Found the swivel elbow was missing customer stated it was broken Removed the plug the was installed. Replaced the elbow and clamped it in place. Reattached to the outdoor sprayer and reinstalled the access panel. Work completed				
	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
	Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes

Part

Line# 1	Item #	Description			
	USERPART	Elbow			
	Model #	Serial #	Part tag		
	Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight \$0.00

Notes

Submitted	Labor Amt	\$380.00	Approved	Labor Amt	\$285.00
	Parts & Freight	\$21.88		Parts & Freight	\$21.88
	Total	\$401.88		Total	\$306.88

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.