



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72478
 Promised Date:
 22 OCT 25



WO #: 72478

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date:
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9623 2026 CRUSADER
 KING33
 Serial#: 128431
 Chassis#: 5ZT3CSYB7TG128431
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 10 OCT 25
 Time In:

Job #1 - Internal

CHECK IN NEW UNIT

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: Several fasteners loose/ missing around exterior of coach on trim and j-wrap

CAUSE: Missing. Loose fasteners

CORRECTION: Resecured and installed new fasteners.
 Requesting .3

Labor

Job #	Description	Total
2	MISC LABOUR CODE (WARRANTY)	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: Leveling system out of calibration on auto level

CAUSE: Out of calibration

CORRECTION: Set zero. Tested. Completed
 Requesting .3

Labor

Job #	Description	Total
3	MISC LABOUR CODE (WARRANTY)	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: Top drawer next to stove getting stuck

CAUSE: Retainer clip detached. Binding.

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,





CORRECTION: Performed adjustments and reinstalled retainer tab. Tested. Completed
 Requesting .3

Labor		
Job #	Description	Total
4	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #4:		0.00

Job #5 - Warranty

COMPLAINT: Bottom drawer next to stove getting stuck

CAUSE: Latch misalignment

CORRECTION: Realigned and tested. Completed
 Requesting .2

Labor		
Job #	Description	Total
5	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #5:		0.00

Job #6 - Warranty

COMPLAINT: Cabinet above tv has misaligned wood frame

CAUSE: Fasteners detached

CORRECTION: Resecured with new fasteners. Completed.
 Requesting .2

Labor		
Job #	Description	Total
6	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #6:		0.00

Job #7 - Warranty

COMPLAINT: Entry door and screen door sticking causing hard open/close procedure

CAUSE: Frame catch hitting door

CORRECTION: Performed adjustments and tested. Completed
 Requesting.3

Labor		
Job #	Description	Total
7	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #7:		0.00

Job #PDI1 - Internal

COMPLAINT: PRE-PDI NEW TT - 3.0

CAUSE: Pre

CORRECTION: Completed. See added jobs

Labor		
Job #	Description	Total
PDI1	PDI TRAVEL TRAILER	N/C

Parts				
Part #	Description	Qty	Price	Total
1000	L.P. GAS	5.00	N/C	N/C



W/O: 72478
Promised Date: 23 DEC 25

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #PDI1: 0.00

Job #WIN-STD - Internal

COMPLAINT: WINTERIZE STANDARD

CAUSE: Winterize

CORRECTION: Completed

Labor

Job #	Description	Total
WIN-STD	WINTERIZE RV - BASIC	N/C

Parts

Part #	Description	Qty	Price	Total
21622	ANTIFREEZE	3.00	N/C	N/C

Subtotal for Job #WIN-STD: 0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 23 Dec 2025

Customer #: 1000
MYERS "RV" CENTER,
INC.,

