

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Paid  
 CLAIM 2560015  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 5ZT2LCZB6TB012568  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 048 / 048A  
 ITEM # LCT3411RK  
 DEALER RO # 72588  
 CLAIM START DATE 01/23/2026  
 CLAIM END DATE 01/26/2026

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1      **Operation Code**      **Operational Description**  
 40-106-24-11-001253      Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-23 10:34:16 :: Complaint: Tongue jack is not working  
 Cause: Connector to battery is falling off Correction: Install new connector for power wire to battery from jack  
**Model#**      **Dlr Sub Hrs**      0.50      **Sub Labor Amt** \$95.00  
**Serial#**      **Appr Hrs**      0.10      **Appr Labor Amt** \$19.00

#### Notes

The time requested is excessive for this repair, time adjusted. NVCB .10 to replace the missing wire terminal. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

### Part

Line# 1      **Item #**      **Description**  
 USERPART      Connector  
**Model #**      **Serial #**      **Part tag**  
**Sub Qty**      1.00      **Sub Dlr Price**      \$0.95      **Sub Freight**      \$0.00  
**Appr Qty**      1.00      **Appr Dlr Price**      \$0.95      **Appr Freight**      \$0.00

#### Notes

### Labor

Line# 2      **Operation Code**      **Operational Description**  
 30-100-24-00-001048      Cabinet or Closet Shelf - Interior/Cabinetry/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-23 10:38:03 :: Complaint: Towel rack above toilet is falling off Cause: Missing screws Correction: Realigned towel rack and installed new screws to hold in place  
**Model#**      **Dlr Sub Hrs**      0.50      **Sub Labor Amt** \$95.00  
**Serial#**      **Appr Hrs**      0.20      **Appr Labor Amt** \$38.00

#### Notes

The time requested is excessive for this repair, time adjusted. NVCB .20 to secure the loose towel rack. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met. Dp.

### Part

Line# 1      **Item #**      **Description**  
 USERPART      Screws  
**Model #**      **Serial #**      **Part tag**  
**Sub Qty**      1.00      **Sub Dlr Price**      \$1.90      **Sub Freight**      \$0.00  
**Appr Qty**      1.00      **Appr Dlr Price**      \$1.90      **Appr Freight**      \$0.00

**Notes**

---

<b>Submitted</b>	Labor Amt	\$190.00
	Parts & Freight	\$2.85
	Total	\$192.85

<b>Approved</b>	Labor Amt	\$57.00
	Parts & Freight	\$2.85
	Total	\$59.85

---

**DEALER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
I certify that I have performed these repairs consistent with Forest River Policies.

---

**CUSTOMER** \_\_\_\_\_ **DATE** \_\_\_\_\_  
**SIGNATURE**  
All repairs described have been inspected and are satisfactory.