

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794		CLAIM STATUS Paid	
MYERS RV CENTER INC		CLAIM 2540346	
12024 CENTRAL AVE S.E.		CLAIM ORIGIN WEB	
ALBUQUERQUE, NM 87123		ORIGINAL CLAIM ID	
USA		VIN	5ZT2TRJB2SB525510
		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$190.00	SITE/WAREHOUSE	048 / 048B
OWNER INFORMATION		ITEM #	TRT200BHSLE
SARAH ANDREWS		DEALER RO #	72627
923 N HALAGUENO ST		CLAIM START DATE	01/02/2026
Carlsbad, NM 88220		CLAIM END DATE	01/05/2026
USA			
Retail Date of Purchase	10/21/2025	WARRANTY EXPIRATION DATE	10/21/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-73-01-00-000739	Fenderskirt - Exterior/Fender Skirts, Wheel Well/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : stephanie@dealer-advisors.com, 2026-01-02 16:41:54 :: Complaint: Left fender skirt is cracked			
	Cause: Fenderskirt is cracked Correction: Remove 12 screws and scrapped silicone. Began to install new skirt and had to trim 1/4" off the belt rail in order for the new skirt to fit. Install new skirt, silicone the edges with clear silicone			
Model#	Dlr Sub Hrs	0.35	Sub Labor Amt	\$66.50
Serial#	Appr Hrs	0.35	Appr Labor Amt	\$66.50
Notes				
NVCB,Finderskirt replacement.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD				

Part

Line# 1	Item #		Description			
	F100469896		SKIRT, FENDER, 6" X 69", TANDEM/ HC, 1-0008-1-1 (USED AFTER OFFLINE DATE 7/25/2023)			
	Model #		Serial #		Part tag	
	Sub Qty	1.00	Sub Dlr Price	\$28.94	Sub Freight	\$28.13
	Appr Qty	1.00	Appr Dlr Price	\$28.93	Appr Freight	\$28.14
	Notes					

Labor

Line# 2	Operation Code	Operational Description			
	20-73-01-00-000739	Fenderskirt - Exterior/Fender Skirts, Wheel Well/Replace/No Tread Code			
	Complaint, Cause, Correction				
	Original Note : stephanie@dealer-advisors.com, 2026-01-02 16:43:48 :: Complaint: Right fenderskirt is cracked Cause: Fenderskirt is cracked Correction: Took 12 screws out, removed cracked fenderskirt. Cleaned up old silicone and install new fenderskirt. Resealed edge with clear silicone.				
	Model#	Dlr Sub Hrs	0.35	Sub Labor Amt	\$66.50
	Serial#	Appr Hrs	0.35	Appr Labor Amt	\$66.50
	Notes				
	NVCB,Finderskirt replacement.Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD				

Part

Line# 1	Item # F100469896	Description SKIRT, FENDER, 6" X 69", TANDEM/ HC, 1-0008-1-1 (USED AFTER OFFLINE DATE 7/25/2023)			
----------------	-----------------------------	---	--	--	--

Model #		Serial #		Part tag	
Sub Qty	1.00	Sub Dlr Price	\$28.94	Sub Freight	\$28.14
Appr Qty	1.00	Appr Dlr Price	\$28.93	Appr Freight	\$28.15

Notes

Submitted	Labor Amt	\$133.00	Approved	Labor Amt	\$133.00
	Parts & Freight	\$114.15		Parts & Freight	\$114.15
	Total	\$247.15		Total	\$247.15

DEALER	DATE
SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.	

CUSTOMER	DATE
SIGNATURE	
All repairs described have been inspected and are satisfactory.	