

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2560079
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2AVGC7TG815468
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 452 / 452
 ITEM # AVT18DBS-452
 DEALER RO # 72767
 CLAIM START DATE 01/23/2026
 CLAIM END DATE 01/27/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 40-196-24-11-001297 Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2026-01-23 11:09:55 :: Complaint: Wires under the slider are exposed Cause: Wires were not installed under baseboards Correction: Remove the baseboard and install P clamp to hold wires back, reinstall baseboard

Model#	Dlr Sub Hrs	0.50	Sub Labor Amt	\$95.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes

NVCB,R&RI base board secure wire. Per dealers description of this repair. This authorization is pending ALL requirements of repair code have been met.TD

Part

Line# 1	Item #	Description			
	USERPART	P Clamp			
	Model #	Serial #		Part tag	
	Sub Qty	Sub Dlr Price	\$2.85	Sub Freight	\$0.00
	Appr Qty	Appr Dlr Price	\$2.85	Appr Freight	\$0.00

Notes

Submitted	Labor Amt	\$95.00	Approved	Labor Amt	\$57.00
	Parts & Freight	\$2.85		Parts & Freight	\$2.85
	Total	\$97.85		Total	\$59.85

DEALER _____ DATE _____
 SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE
 All repairs described have been inspected and are satisfactory.