

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794
 MYERS RV CENTER INC
 12024 CENTRAL AVE S.E.
 ALBUQUERQUE, NM 87123
 USA

CLAIM STATUS Paid
 CLAIM 2529124
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TRPU17TB035040
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 080 / 080
 ITEM # RPT185-80
 DEALER RO # 72180
 CLAIM START DATE 12/16/2025
 CLAIM END DATE 01/02/2026

Labor rate: \$190.00
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 30-100-24-00-001046 Cabinet Door - Interior/Cabinetry/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-16 13:46:43 :: Complaint: Upper cabinet door to the left of the stove top is off. Cause: Stripped screws Correction: Removed stripped screws and replaced with two new larger diameter screws and adjusted the door.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes

Part

Line# 1 **Item #** **Description**
 USERPART Screws
Model # **Serial #** **Part tag**

Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight	\$0.00

Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 30-100-02-00-001044 Drawer Guides or Tracks, pair - Interior/Cabinetry/Adjust/No Tread Code
Complaint, Cause, Correction
 Original Note : stephanie@dealer-advisors.com, 2025-12-16 13:49:11 :: Complaint: Drawer guides at the top drawer to the left of the cook top are stuck Cause: Drawer guide had a slight bend Correction: Used a pair of pliers and straighten the bend out

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$38.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$38.00

Notes

Submitted	Labor Amt	\$95.00	Approved	Labor Amt	\$95.00
	Parts & Freight	\$2.85		Parts & Freight	\$2.85
	Total	\$97.85		Total	\$97.85

DEALER SIGNATURE _____ DATE _____

CUSTOMER SIGNATURE _____ DATE _____

I certify that I have performed these repairs consistent with Forest River Policies.

All repairs described have been inspected and are satisfactory.