



12024 Central Ave SE ★ Albuquerque NM 87123
 www.MYERSRV.com
 (505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72183-1
 Promised Date:
 22 JAN 26



WO #: 72183-1

Customer Name: 1000 - MYERS "RV"
 CENTER, INC.

Completed Date: 24 JAN 26
 Invoice#:
 Author: ADVISOR
 Stock Desc: 9586 2026 R-POD RP-153
 Serial#: 035109
 Chassis#: 4X4TRP518TB035109
 Miles/Hrs:
 Tag#:
 Purchased Date:
 Warranty Date:

Date In: 23 DEC 25
 Time In:

Job #2 - Warranty

COMPLAINT: Broken cabinet door under kitchen sink

CAUSE: Component failure

CORRECTION: Need to order cabinet door. Install cabinet door and transfer hardware. Cabinet door measures 11 inches across by 32 1/2 tall
 Requesting - 1hour

Labor

Job #	Description	Total
2	CABINET DOOR R&R	76.00

Parts

Part #	Description	Qty	Price	Total
F100550210	DOOR, CABINET FLAT PANEL 11" X 32.5" BRIGHTON WHITE (670133)	1.00	25.28	25.28

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	24.37	24.37

Subtotal for Job #2: 125.65

Job #3 - Warranty

COMPLAINT: Voids and gaps on silicone at kitchen sink

CAUSE: Incorrect installation

CORRECTION: Removed silicone all around sink loosened sink, adjusted sink, and attempted to close gap between countertop and sink. Fasteners are tightened to Max thread sink makes contact with microwave cabinetry. Clean surface and resealed.
 Requesting 1.5hours

Labor

Job #	Description	Total
3	KITCHEN SINK	190.00

Customer #: 1000
 MYERS "RV" CENTER,
 INC.,



Subtotal for Job #3: 190.00

Job #4 - Warranty

COMPLAINT: Shower surround, has voids and gaps on sealant

CAUSE: Incorrect installation

CORRECTION: Removed sealant, clean surface and applied new sealant in appropriate areas
Requesting 2hours

Labor

Job #	Description	Total
4	SHOWER SURROUND	152.00

Subtotal for Job #4: 152.00

Job #5 - Warranty

COMPLAINT: Voids and gaps on sealant at bathroom countertop

CAUSE: Incorrect installation

CORRECTION: Debris embedded into area behind faucet is not sealed. Had to remove faucet to gain access to rear part of countertop. Clean surface and applied New Zealand reinstalled faucet and zip tied vacuum breaker for black tank flesh. Leak tested faucet no leaks noted.
Requesting 1.5hours

Labor

Job #	Description	Total
5	BATHROOM COUNTERTOP	228.00

Subtotal for Job #5: 228.00

Parts Total: 25.28
 Labour Total: 646.00
 Sublet Total: 0.00
 Extras Total: 24.37

WORK ORDER TOTAL: 695.65

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 24 Jan 2026

W/O: 72183-1
Promised Date: 23 JAN 26



Customer #: 1000
MYERS "RV" CENTER,
INC.,

