

# FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0008794  
 MYERS RV CENTER INC  
 12024 CENTRAL AVE S.E.  
 ALBUQUERQUE, NM 87123  
 USA

CLAIM STATUS Paid  
 CLAIM 2562441  
 CLAIM ORIGIN WEB  
 ORIGINAL CLAIM ID  
 VIN 4X4TUMA23TB035532  
 CHASSIS VIN  
 MILEAGE 0  
 SITE/WAREHOUSE 080 / 080B  
 ITEM # UMT25RL-80  
 DEALER RO # 72473  
 CLAIM START DATE 01/27/2026  
 CLAIM END DATE 01/27/2026

Labor rate: \$190.00  
 OWNER INFORMATION

Retail Date of Purchase WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

Line# 1      **Operation Code**      **Operational Description**  
 20-46-01-00-000733      Screw Cover - Exterior/Windows/Replace/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-27 11:10:44 :: Complaint: Window frame near sofa is missing a lot of screws Cause: Window frame missing screws Correction: Installed all missing screws in window frame

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$19.00
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$19.00

Notes

### Part

Line# 1      **Item #**      **Description**  
 USERPART      Screws  
**Model #**      **Serial #**      **Part tag**

Sub Qty	1.00	Sub Dlr Price	\$0.95	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$0.95	Appr Freight	\$0.00

Notes

### Labor

Line# 2      **Operation Code**      **Operational Description**  
 30-100-24-00-001046      Cabinet Door - Interior/Cabinetry/Repair/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-27 11:12:42 :: Complaint: Cabinet door in bedroom has fallen off Cause: Screws are missing Correction: Install new screws to hold door in place

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$57.00
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$57.00

Notes

### Part

Line# 1      **Item #**      **Description**  
 USERPART      Screws  
**Model #**      **Serial #**      **Part tag**

Sub Qty	1.00	Sub Dlr Price	\$2.85	Sub Freight	\$0.00
Appr Qty	1.00	Appr Dlr Price	\$2.85	Appr Freight	\$0.00

Notes

### Labor

**Line# 3**      **Operation Code**      **Operational Description**  
 30-102-12-00-001096      Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/  
 Resecure or Tighten/No Tread Code  
**Complaint, Cause, Correction**  
 Original Note : stephanie@dealer-advisors.com, 2026-01-27 11:14:25 :: Complaint: Trim above bedroom door is coming off Cause: Door trim is falling off, screw has pulled out of wall Correction: Installed new screw to hold door trim in place

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.10	<b>Sub Labor Amt</b>	\$19.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.10	<b>Appr Labor Amt</b>	\$19.00

**Notes**

<b>Part Line# 1</b>	<b>Item #</b>	<b>Description</b>			
	USERPART	Screw			
	<b>Model #</b>	<b>Serial #</b>	<b>Part tag</b>		
	Sub Qty	1.00	Sub Dlr Price	\$0.95	Sub Freight \$0.00
	Appr Qty	1.00	Appr Dlr Price	\$0.95	Appr Freight \$0.00

**Notes**

<b>Submitted</b>	Labor Amt	\$95.00	<b>Approved</b>	Labor Amt	\$95.00
	Parts & Freight	\$4.75		Parts & Freight	\$4.75
	Total	\$99.75		Total	\$99.75

\_\_\_\_\_  
**DEALER**      **DATE**  
**SIGNATURE**  
 I certify that I have performed these repairs consistent with Forest River Policies.

\_\_\_\_\_  
**CUSTOMER**      **DATE**  
**SIGNATURE**  
 All repairs described have been inspected and are satisfactory.