



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 72271
Promised Date:
44 NOV 25



WO #: 72271

Customer Name: 60322 - ARMSTRONG,
VAL

Completed Date: 09 MAR 26

Invoice#:

Author: BRIAN

Stock Desc: 2024 APEX 265RBSS

Serial#: 5ZT2CXSB0RS047066

Chassis#:

Miles/Hrs:

Tag#: 6855

Purchased Date:

Warranty Date:

Date In: 27 AUG 25

Time In:

Job #0 - Warranty

CLAIMS: 2534030 / 2597580

Subtotal for Job #0: 0.00

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES SHOWER LEAKS ON FLOOR WHILE IN USE / WATER DAMAGE
ON PANELING AND SLIDE FACIA

CAUSE: Water leak damaged trim and door jam

CORRECTION: Recommend replacement

Need 1 more batten trim and door jam 4 x78

2 batten trim pieces are here

Battens and stile installed when the door was replaced

Work complete

Labor

Job #	Description	Total
1	SHOWER LEAK	190.00

Parts

Part #	Description	Qty	Price	Total
F100411404	STILE, CASINO BISQUE 18MM X 4" X 96"	1.00	12.81	12.81
F100411404	STILE, CASINO BISQUE 18MM X 4" X 96"	1.00	27.85	27.85
F100411428	TRIM, BATTEN 7/8" X 8' #195 VERTICAL OASIS	2.00	1.78	3.56
F100411428	TRIM, BATTEN 7/8" X 8' #195 VERTICAL OASIS	1.00	5.43	5.43

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	201.81	201.81

Subtotal for Job #1: 441.46

Job #2 - Warranty

COMPLAINT: BATHROOM SLIDING DOOR LOOSE

Customer #: 60322
ARMSTRONG, VAL





CAUSE: Strap broke on bathroom barn door
 Taped door open tape pulled paint off the door

CORRECTION: Removed the broken strap removed one screw
 New strap with snap was cut to fit and screwed back in place
 The tape used to hold door in the open position when removed peeled the paint off the door and door jam
 Recommend replacement of the door and door jam or color match the paint and touch up
 Hood for approval
 Door size 36 x 73
 Door jam size 4x 78
 Removed. Both top trims
 Unlatched the door and removed the door
 Unboxed the new door removed all hardware from the old door and installed it on the new door
 Removed the top rail from the ceiling
 Removed the stile on the right side , removed both vertical batten trims from either side of the stile and the two baseboard battens
 Pulled all the nails and staples
 Cut the new stile to size and nailed it in place
 Cut and installed both vertical batten. Trims and cut and installed both baseboard battens
 Puttied all nail and staple holes
 Reinstalled top rail
 Installed the door and latched it in place
 Installed the magnet plate on the stile
 Installed the snap button
 Installed both top trims on either side of the top of the door
 Still need the stile for the left side will have to be ordered
 QC by Brian
 Removed last damaged facia cut and installed new facia puttied nail holes
 Work completed

Labor

Job #	Description	Total
2	SHOWER DOOR	190.00

Parts

Part #	Description	Qty	Price	Total
04-016553	STRAP - PLASTIC, W/SNAP	1.00	8.73	8.73
F100390375	DOOR, CASINO BISQUE 1-3/8" X 36" X 73" W/ CENTER LOCKS	1.00	81.24	81.24

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	196.76	196.76
FRT	CRATE FEE	1.00	90.00	90.00
FRT	SHIPPING & HANDLING CHARGES	1.00	54.39	54.39

Subtotal for Job #2: 621.12

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES AWNING MISSING CAPS AND ARM CRACKED

CAUSE: Missing awning front caps

CORRECTION: Attached new awning front caps
 Work completed

Labor

Job #	Description	Total
7	AWNING	57.00

Parts

Part #	Description	Qty	Price	Total
F100358755	AWNING COVER MOTOR SIDE	1.00	6.37	6.37
F100358756	AWNING COVER IDLER SIDE FRONT	1.00	6.37	6.37



Subtotal for Job #7: 69.74

W/O: 72271
Promised Date: 11 NOV 25

Parts Total: 152.36
Labour Total: 437.00
Sublet Total: 0.00
Extras Total: 542.96
WORK ORDER TOTAL: 1,132.32

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 09 Mar 2026

Customer #: 60322
ARMSTRONG, VAL

